

Meanders, T. 11 N., R. 29 E.

Chains N. $59\frac{1}{4}^\circ$ W., 1.90 chs.N. $71-3/4^\circ$ W., 5.80 chs.N. $44\frac{1}{2}^\circ$ W., 3.30 chs.N. 3° E., 4.59 chs. To meander cor. of fractl. secs. 6
and 7

Land, level. Soil, rocky.

Timber, none. Undergrowth, none.

General drainage, NE. Grazing, none.

Thence in sec. 6

Along level rocky shore line

N. 3° E., 16.00 chs.N. 6° W., 18.30 chs.N. $8\frac{1}{2}^\circ$ W., 17.10 chs.N. $24\frac{1}{4}^\circ$ W., 11.60 chs.N. $9\frac{1}{2}^\circ$ W., 7.20 chs.N. $58-3/4^\circ$ W., 1.40 chs.S. 88° W., 1.30 chs.S. 75° W., 3.80 chs.N. $9^\circ 20'$ W., 14.50 chs. To meander cor. of fractl. sec. 6

Land, level. Soil, rocky.

Timber, none. Undergrowth, none.

General drainage, NE. Grazing, none.

Latitudes, Departures, and Closing errors.

Lines designated	True bearings	Distances Chs	N Chs	S Chs	E Chs	W Chs
N. boundary	West	8.35 ✓				8.35 ✓
	S. $89^\circ 55'$ W.	35.27 ✓		.05 ✓		35.27 ✓
W. boundary	South	482.67 ✓		482.67 ✓		
S. boundary	East	157.52 ✓			157.52 ✓	
Meanders Sec. 32	N. $24^\circ 19'$ E	6.15 ✓	5.60 ✓		2.53 ✓	
" 33	N. $21\frac{1}{2}^\circ$ E	5.30 ✓	4.93 ✓		1.94 ✓	
	N. 10° E	6.20 ✓	6.11 ✓		1.08 ✓	
	N. $38\frac{1}{2}^\circ$ E	4.70 ✓	3.68 ✓		2.93 ✓	
	N. 20° E	3.40 ✓	3.19 ✓		1.16 ✓	
	N. $26-3/4^\circ$ E	19.50 ✓	17.41 ✓		8.78 ✓	
	N. 12° E	5.00 ✓	4.89 ✓		1.04 ✓	
	N. 9° E	8.60 ✓	8.49 ✓		1.34 ✓	
	N. $45\frac{1}{4}^\circ$ E	5.90 ✓	4.15 ✓		4.19 ✓	
	N. $27\frac{1}{2}^\circ$ E	6.70 ✓	5.94 ✓		3.09 ✓	
	N. $15^\circ 21'$ E	16.21 ✓	15.63 ✓		4.29 ✓	