

DEPENDENT RESURVEY OF EAST BOUNDARY OF T. 20 N., R. 53 E.

Chains

30
T21N
R53E R54E
S36 S31
S1 S5
T20N
1933

Pits impracticable; no stone available for mound.

Deposit a glass bottle at base of post.

Land, gently rolling.

Soil, sandy and gravelly with some clay, 2nd and 3rd rate.

Timber, none. Undergrowth, sagebrush.

General drainage, N. Grazing, poor.

INDEPENDENT RESURVEY OF PORTION OF SOUTH BOUNDARY
T. 20 N., R. 53 E.

SUPERSEDING THE SURVEYS EXECUTED BY E. L. BRIDGES AND
J. W. EATON, U. S. DEPUTY SURVEYORS IN 1879

Random lines.

From the cor. of secs. 33 and 34, on S. bdy. of T.,
hereinafter described.

East, along S. bdy. of T.

219.80 Intersect W. bdy. of T. 19 N., R. 54 E.

Set an iron post, 3 ft. long, 3 ins. diam., 27 ins. in
the ground, for the cor. of Tps. 19 and 20 N., R. 53 E.,
with brass cap mkd.

T20N
R53E T19W
S36 S6
S1 R54E
T19N
R53E
1927

raise a mound
of stone, 3 ft. base, 3 ft. high, W. of cor.

From this point the $\frac{1}{4}$ sec. cor. on W. bdy. of sec. 6,
hereinbefore described, bears N. $0^{\circ} 16'$ E., 9.50 chs.
dist.From same point the cor. of secs. 1, 6, 7, and 12,
hereinbefore described, bears S. $0^{\circ} 16'$ W., 30.73 chs.
dist.

True lines.

From the cor. of Tps. 19 and 20 N., R. 53 E.

West, along S. bdy. sec. 36.

Over mountainous bench land, through scattering second
growth timber and dense undergrowth.

Asc. general broken NE. slope 25 ft. to 31.05 chs.