

DEPENDENT RESURVEY OF PORTION OF SOUTH BOUNDARY OF  
T. 20 N., R. 53 E.

## Chains

Land, gently rolling 61.00 chs.; rolling 19.00 chs.  
Soil, E. half clay loam; W. half gravelly; some sand  
with gravel surfaces; 2nd and 3rd rate.

Timber, none.

Undergrowth, sagebrush, practically no grass.

General drainage, N.

Grazing, poor.

From sec. cor.

N. 89° 10' W., along S. bdy. sec. 31.

Over rolling land, through dense undergrowth.

Asc. general E. slope 115 ft. to 56.00 chs.

21.50 Unused road, bears N. 65° E. and S. 65° W.

42.20 Unused road, bears N. 55° E. and S. 55° W.

43.76 Proportionate point for  $\frac{1}{4}$  sec. cor.

Set an iron post, 3 ft. long, 1 in. diam., 27 ins. in  
the ground, for the  $\frac{1}{4}$  sec. cor. of sec. 31, with brass  
cap mkd.

$\frac{1}{4}$  S 31

1933

18x18x12 ins., E. and W. of post, 3 ft. dist. dig pits,

Deposit glass bottle at base of post.

44.00 Wash from canyon, 15 lks. wide, 10 ins. deep, drains  
N. 60° E.

56.00 Base of mountains, bears N. 15° E. and SW.

Thence over mountainous land.

Asc. rocky SE. slope 300 ft. to

76.87 Proportionate point for Tp. cor.

Set an iron post, 3 ft. long, 3 ins. diam., 12 ins. in  
the ground to bedrock, with a glass bottle deposited at  
the base, and in a mound of stone, for the cor. of Tps.  
19 and 20 N., Rs. 52 and 53 E., with brass cap mkd.

T20N

R52E R53E

S31 S31

S1 S6

T19N

1933

The cor. of secs. 1, 2, 35, and 36, Tps. 19 and 20 N.,  
R. 52 E., bears N. 82° 48' W., 88.22 chs. dist., a  
granite stone, 17x11x10 ins., above ground, firmly set,  
marked and witnessed as described in the official  
record.

The  $\frac{1}{4}$  sec. cor. bet. secs. 1 and 6, Tps. 19 N., Rs. 52  
and 53 E., bears S. 11° 04' E., 40.29 chs. dist., a  
stone, 14x12x10 ins. above ground, firmly set, marked  
and witnessed as described in the official record.