4-673b

DEPENDENT RESURVEY OF EAST BOUNDARY T. 21 N., R. 53 E.

Chains

The original sec. cor., which is a stone, 16x10x8 ins., above ground, firmly set, marked and witnessed as described in the official record, alongside which

Set an iron post, 3 ft. long, 2 ins. diam., 27 ins. in the ground, for the cor. of secs. 6 and 7, with brass cap mkd.

R53E R54E S6 S7

dig pits, 18x18x12 ins., one in each section, 3 ft. dist.

Deposit glass bottle at base of post.

Land, gently rolling.
Soil, sandy and gravelly clay loam, 3rd rate.
Timber, none.
Undergrowth, sagebrush.
General drainage, W.
Grazing, poor.

N. 0° 10' E., along W. bdy. sec. 6.

Over gently rolling land through dense undergrowth.

36.45 Northing of 40.00 chs. from the cor. of secs. 1 and 12

Set an iron post, 3 ft. long, 1 in. diam., 27 ins. in the ground, for the 4 sec. cor. of sec. 1, with brass cap mkd.

1933

dig pits, 15x15x12 ins., N. and S. of post, 3 ft. dist.

Deposit glass bottle at base of post

The original \(\frac{1}{4}\) sec. cor., which is a stone, 15x10x6 ins., above ground, firmly set, marked and witnessed as described in the official record, alongside which

Set an iron post, 3 ft. long, 1 in. diam., 27 ins. in the ground, for the # sec. cor. of sec. 6, with brass cap mkd.

\$6

dig pits,

15x15x12 ins., N. and S. of post, 3 ft. dist.

Deposit glass bottle at base of post.

Thence

N. 0° 11' E., with continuous measurement.

40.31