

Survey of the subdivisions of fractional T. 45 $\frac{1}{2}$  N., R. 24 E.

## Chains.

west on line, 11.62 chs. distant from the standard  $\frac{1}{4}$  sec. cor. of sec. 33, which is a basalt stone, firmly set and properly marked and witnessed as described in the field notes of T. 46 N., R. 24 E. At the point of intersection, set an iron post, 3 ft. long, 2 ins. in diam., 27 ins. in the ground, for the closing cor. of secs. 34 and 35, with brass cap mkd.

T46N R24E  
S33  
S34 S35  
T45 $\frac{1}{2}$ N R24E  
C C  
1927

Raise a mound of stone 3 ft. base, 2 ft. high, S. of the corner.

Land: rolling. Soil: rocky and gravelly clay.

Undergrowth: sage. Fair growth of grass.

At a point west on line, 11.675 chs. distant from the standard cor. of secs. 33 and 34, which is a basalt stone, firmly set and properly marked and witnessed as described in the field notes of T. 46 N., R. 24 E., set an iron post, 3 ft. long, 1 in. in diam., 27 ins. in the ground, for the  $\frac{1}{4}$  sec. cor. of sec. 35 only, with brass cap mkd.

S35  
1927

Raise a mound of stone 2 ft. base, 1 $\frac{1}{2}$  ft. high, S. of the cor.

From the cor. of secs. 3, 4, 33 and 34 on the S. Bdy. of the township, which is an iron post, 2 ins. in diam., firmly set and properly marked and witnessed as described in the field notes of T. 45 N., R. 24 E., N. 0° 02' W. bet. secs. 33 and 34.

Desc. abrupt and rocky NW. slope of canyon 140 ft.

5.60 Creek in bottom of Echo Canyon; running water 4 lks. wide, 2 ins. deep, course NE. Asc. SE. slope 130 ft. over outcroppings.