

SUBDIVISIONS T. 30 N., R. 38 E.

Chains Thence desc. along NE. slope 140 ft. to
 77.15 Main ravine, drains N. 75° E., to
 Asc. rocky SE. slope 65 ft. to
 80.91 Intersect Sixth Standard Parallel North, 6.04 chs. W.
 of the standard cor. of secs. 31 and 32, and at point
 of intersection
 Set an iron post, 3 ft. long, 2 ins. dia., 8 ins. in
 the ground to solid rock, in a mound of stone, for the
 closing cor. of secs. 5 and 6, with brass cap mkd
 T31NR38E
 S 31
 S6 S5
 T30NR38E
 CC
 1928
 At base of post deposit a mkd(X) basalt stone, 4x4x4 ins.
 Land, rough mountainous. Soil, rocky, 3rd and 4th rate.
 Timber, none. Undergrowth, sage, willows, yellow top.
 General drainage, SW. and NE. Grazing, fair.

Latitudes, Departures, and Closing Errors.

	Bearing	Dist- ance	Latitudes		Departures	
			N	S	E	W
		Chs	Chs	Chs	Chs	Chs
E. boundary	S.0°21'E	39.52		39.52	.24	
	S.0°26'E	279.94		279.94	2.12	
	S.0°32'W	40.18		40.18		.37
	S.0°36'E	40.00		40.00	.42	
Subdivisions	S.89°13'W	79.96		1.09		79.95
	N.1°44'E	80.04	80.00		2.42	
	N8°07'W	80.37	1.24			80.36
	S85°47'W	39.93		2.94		39.82
	West	40.18				40.18
	S89°59'W	39.82		.01		39.82
	N89°33'W	40.17	.31			40.17
	N.0°51'E	80.00	80.00		1.19	
	N88°34'W	80.40	2.01			80.38
	N.0°14'W	40.22	40.22			.16
	N.0°32'W	40.00	40.00			.37
	N89°51'W	77.68	.20			77.68
W. boundary	N.1°13'W	156.07	156.03			3.31
	N89°06'E	1.59	.02		1.59	
	North	3.77	3.77			
N. boundary	East	473.86			473.86	
Convergency					.36	
			403.80	403.68	482.20	482.57
			403.68			482.20
Error in latitude			.12			
Error in departure						.37