

Independent Resurvey of the Fourth Standard Parallel North
through R. 34 E.

Chains. Undergrowth: sage and scattering buckbrush. Fair growth
of grass.

N. 89° 59' W. on a true line, on the S. Bdy. of sec. 31.
Desc. 130 ft. along S. slope to dry wash, over broken
and mountainous land.

.36 Set an iron post 3 ft. long, 2 ins. in diam., 6 ins. in
the ground, to solid rock, in a mound of stone 3 ft.
base, 30 ins. high, for the witness standard cor. of
secs. 31 and 32, with brass cap mkd.

	S	C	
T21N		R34E	
S31		S32	WC
1928			

At base of post deposit a granite stone 10 x 8 x 8 ins.
marked with cross (x).

1.27 Fall 42 lks. S. of the original standard cor. of secs. 31
and 32, which is a granite stone, 12 x 9 x 6 ins., set
in a small mound of stone, marked with 5 grooves on the
E. face and 1 groove on the W. face. I destroy all
evidence of this corner.

8.80 Dry wash, drains SE. Asc. NE. slope 360 ft.

15.50 Top of spur, projects SE. Continue ascent along broken
S. slope 240 ft.

40.00 Set an iron post 3 ft. long, 1 in. in diam., 27 ins. in
the ground, for the standard $\frac{1}{4}$ sec. cor., with brass
cap mkd.

	S	C
$\frac{1}{4}$ S31		
1928		

Raise a mound of stone, 2 ft. base, 1½ ft. high, N. of
the cor. At base of post deposit a granite stone, 16 x
8 x 4 ins., marked with cross (x).