

Survey of the N. Bdy. of T. 21 N., R. 34 E.

Chains.

From the cor. of Ts. 21 and 22 N., Rs. 34 and 35 E.,
hereinbefore described,

West, on a true line, on the S. Bdy. of sec. 36, T. 22
N., R. 34 E.

Over slightly rolling land. Gradual Ascent.

16.20 Dry shallow channel, drains NE.

27.67 True point for the $\frac{1}{4}$ sec. cor. on the N. Bdy. of sec. 1,
hereinafter determined. Set an iron post, 3 ft. long,
1 in. in diam., 30 ins. in the ground, for the $\frac{1}{4}$ sec.
cor. of sec. 1 only, with brass cap mkd.

$\frac{1}{4}$ S1
1928

Pits impracticable and no other accessories available.

40.00 Set an iron post, 3 ft. long, 1 in. in diam., 30 ins.
in the ground, for the $\frac{1}{4}$ sec. cor. of sec. 36 only,
with brass cap mkd.

$\frac{1}{4}$ S36
1928

Pits impracticable and no other accessories available.

80.00 Set an iron post, 3 ft. long, 2 ins. in diam., 30 ins.
in the ground, for the cor. of secs. 35 and 36 only,
with brass cap mkd.

T22N R34E
S35 S36
S2
T21N R34E
1928

Pits impracticable and no other accessories available.

Land: nearly level with drainage NE.

Soil: sandy clay of medium texture containing a strong
alkaline content.

Undergrowth: shadscale and greasewood. Scattering growth
of salt grass.

West on a true line, on the S. Bdy. of sec. 35, T. 22 N.,
R. 34 E.

Over nearly level land.

27.74 True point for the $\frac{1}{4}$ sec. cor. on the N. Bdy. of sec. 2,
hereinafter determined.