

418

INDEPENDENT RESURVEY OF THE EAST BOUNDARY OF T. 16 N., R. 51 E.

Chains

Independent resurvey, superseding the survey executed by E. B. Monroe, U. S. Deputy Surveyor, in 1884.

From the standard cor. of Tps. 16 N., Rs. 51 and 52 E., which is an iron post, 3 ins. in diam., firmly set, marked and witnessed as described in the official record.

North, bet. secs. 31 and 36.

Over mountainous bench land, through scattering timber and dense undergrowth; desc. stony NW. slope 30 ft. to

11.20 Draw, drains N. 50° E.; asc. stony SE. slope 15 ft. to

16.00 Desc. general NW. slope 10 ft. to

38.80 Desc. general NE. slope 10 ft. to 52.20 chs.

40.00 Find no trace of original $\frac{1}{4}$ sec. cor.

Set an iron post, 3 ft. long, 1 in. diam., 27 ins. in the ground, for $\frac{1}{4}$ sec. cor., with brass cap mkd.

$\frac{1}{4}$
 S36 | S31
 1933

from which

A juniper, 8 ins. diam., bears N. 82° E., 35 lks. dist., mkd. BT only.

A juniper, 6 ins. diam., bears N. 68° W., 19 lks. dist., mkd. BT only.

52.20 Desc. general NW. slope 40 ft. to 68.00 chs.

64.10 Wash in draw, 15 lks. wide, 38 ins. deep, drains N. 45° E.

68.00 Desc. general broken NE. slope 20 ft. to

80.00 Find no trace of original sec. cor.

Set an iron post, 3 ft. long, 2 ins. in diam., 27 ins. in the ground, for cor. of secs. 25, 30, 31, and 36, with brass cap mkd.

T16N
 R51E R52E
 S25 | S30
 S36 | S31
 1933

No suitable trees available within limits.

Deposit red granite stone, 7x4x2 ins., mkd. X at base of post.

Land, mountainous bench. Soil, 20 ins. sand and gravel, stony, 4th rate. Timber, mountain mahogany, pinon, juniper. Undergrowth, sagebrush. General drainage, NE. Grazing, poor.