

T. 19 N., R. 36 E.

$\frac{1}{4}$  S6  
1929

At base of post deposit a mkd(X)granite stone, 4x6x6 ins.

LATITUDES, DEPARTURES AND CLOSING ERRORS.

Lines designated	True bearings	Dist-ances chs	Latitudes		Departures	
			N chs	S chs	E chs	W chs
E. boundary	S. 0° 27' W	480.00		480.00		3.77
S. boundary	West	478.21				478.21
W. boundary	North	480.00	480.00			
N. boundary	S89°56'E	481.37		.56	481.37	
Convergency					.60	
			480.00	480.56	481.97	481.98
				480.00		481.97
Error in Latitude				.56		.01
Error in Departure						.01

GENERAL DESCRIPTION.

The greater part of this township is located in a chain of high rugged mountains. With the exception of areas of rolling mountainous land in sections 30 and 31, practically all of the remainder of the township can be classified as rough mountainous, many of the slopes being precipitous and impassable.

The canyons, ravines and washes have, almost without exception, steep, rocky sides, and gravelly, boulder-strewn, narrow bottoms.

Steep rock slides and ledges abound in the more mountainous parts.

Pinon is the predominating timber with scattering stands of juniper.

The predominant types of undergrowth are, sagebrush, greasewood, buckbrush and willow.

So far as can be learned, no mineral of any type of value, has been found in the township.

Several streams of running water are found in the higher portions of the township, with Bench and Horse Creeks supplying the major portion for stock watering and domestic uses