

Subdivisions T. 30 N., R. 29 E.

Chains

S 4
 $\frac{1}{4}$
 S 9
 1927

- At base of post deposit a marked(X) stone, 4x5x6 ins.
- 47.35 Road, bears N. 15° E. to Farrel and S. 15° W. to Seven
Troughs. Thence over rough mountainous land
- 60.05 Wash, 10' lks. wide, 1 ft. deep, drains S. 30° E.
- 79.92 The cor. of secs. 4, 5, 8 and 9
- Land, rolling to rough mountainous. Soil, rocky to
gravelly loam. Timber, none. Undergrowth, sagebrush.
General drainage, SE. Grazing, poor.
- N. 0° 03' W., bet. secs. 4 and 5
- Over rough mountainous land
- Desc. rocky NE. slope 125 ft. to
- 12.55 Head of ravine, drains E. Asc steep rocky SE. slope 80 ft.
- 26.35 Spur, projects S. 80° E. Desc. NE. slope 135 ft. to
- 40.00 Set an iron post, 3 ft. long, 1 in. dia., 18 ins. in
the ground to solid rock, in a mound of stone, for the
 $\frac{1}{4}$ sec. cor., with brass cap mkd

$\frac{1}{4}$
 S5 | S4
 1927

- At base of post deposit a marked(X) stone, 6x6x7 ins.
- 44.10 Head of ravine, drains NE.
- Asc. SE. slope
- 47.37 Intersect Sixth Standard Parallel ^{North} 1.54 chs. W. of the
standard cor. of secs. 32 and 33, which is described in
Book "B" under Group No. 112, containing the field notes
of survey of T. 31 N., R. 29 E., which survey was made
in conjunction with the survey of this fractional
township. At point of intersection
- Set an iron post, 3 ft. long, 2 ins. dia., 6 ins. in the
ground to solid rock, in a mound of stone, for the
closing cor. to secs. 4 and 5, with brass cap mkd