

Subdivisions T. 30 N., R. 29 E.

Chains

$\frac{1}{4}$  — S 6  
 S 7  
 1927

At base of post deposit a marked (X) stone, 4x5x6 ins.

60.00 Rocky ridge, bears N. 45° W. and S. 45° E.

Desc. steep rocky NE. slope 380 ft. to

79.20 The cor. of sees. 5, 6, 7 and 8

Land, rough mountainous. Soil, rocky.

Timber, none. Undergrowth, sagebrush.

General drainage, NW, SW, and SE. Grazing, poor.

N. 0° 04' W., bet. sees. 5 and 6

Over rough mountainous land. Desc. steep rocky NE. slope 310 ft. to

14.70 Desc. N. slope 90 ft. to

22.70 Desc. NE. slope 80 ft. to

28.30 Intermittent seeping stream of water in wash, 30 lks. wide, 5 ft. deep, (Burnt Canyon), course S. 70° E.

Asc. steep rocky SW. slope 170 ft. to

36.55 Asc. steep rocky SE. slope 190 ft. to see. cor.

40.00 Set an iron post, 3 ft. long, 1 in. dia., 14 ins. in the ground to solid rock, in a mound of stone, for the  $\frac{1}{4}$  sec. cor., with brass cap mkd

$\frac{1}{4}$   
 S6 | S5  
 1927

At base of post deposit a marked (X) stone, 4x6x8 ins.

47.45 Intersect Sixth Standard Parallel <sup>North</sup> 1.65 chs. W. of the

standard cor. of sees. 31 and 32, which is described in Book "B" under Group No. 112, containing the field notes of the survey of T. 31 N., R. 29 E., which survey was made in conjunction with the survey of this fractional township, at point of intersection

Set an iron post, 3 ft. long, 2 ins. dia., 20 ins. in the ground to solid rock, in a mound of stone, for the closing cor. to. sees. 5 and 6, with brass cap mkd