

150

12

DEPENDENT RESURVEY OF THE E. BDY. T. 18 S., R 62 E.

Chains	
42.80	Top of ledges, 40 ft. high, facing on spur, projecting S. 60° E.; desc. along steep N. slope.
45.30	Head of rocky draw, drains S. 60° E.; asc. abrupt SE. slope 300 ft.
49.30	Top of ledges, 50 ft. high, facing SE., bears NE. and SW. Continue over broken top of spur.
59.80	Limestone ledges, 10 to 40 ft. high, facing N., bears E. and W.; desc. over precipitous N. slope.
78.50	Rocky ravine, course E.; continue along rocky SE. slope.
80.00	Set an iron post 3 ft. long, 2 ins. diam., 27 ins. in the ground, for cor. of secs. 1 and 12 only, with brass cap mkd.

SEC 1 T18S

North corner line to be set in R62E and R63E before mdc

S 1

Land, very rocky and uneven surface; soil thin & dry, brownish yellow, gravelly, sandy, with some molluscs, fine gravel, no stones, no timber, plants common S12 or regular pattern no creosote, etc. - 1933

raise a mound of stone, 4 ft. base, 5 ft. high, W. of cor.

Land, rough mountainous.

Soil, very shallow rocky loam, 3rd and 4th rate.

Undergrowth, creosote, buckbrush, cacti.

No timber.

surface condition

North, on true line along the E. bdy. of sec. 1. Over rough mountainous land, through scattering undergrowth.

elevation

Asc. steep SE. slope over loose slide rock.

10.30 Base of limestone ledges, 80 ft. high, facing S., bears W. and NE.

distance from corner

Top of same ledges; continue ascent of S E. slope over numerous small ledges and outcrops.

23.30 Rocky spur, 650 ft. above cor., projects N.; desc. rocky N. slope, 170 ft.

28.00 Head of small rocky gully, drains NE.; asc. 40 ft.

32.20 Small rocky spur, projects NE. about 8 chs.; desc. rocky N. slope, 290 ft.

39.40 Large rocky draw, drains E.; asc. over steep SE. slope.