

196

58

## SUBDIVISION OF T. 18 S., R. 63 E.

## Chains

- $\frac{1}{4}$  S20  
 $\frac{1}{4}$  S29  
 1933
- Continue ascent of SE. slope.
- 50.10 Top of hill, 210 ft. above draw, bears S. 20° E. and N., desc. 80 ft. over rocky SW. slope.
- 61.00 Small wash, drains S.
- 64.30 Draw, drains S. 30° E.; asc. gradually over rocky E. slope 40 ft.
- 71.00 Low rocky spur, projects S. 10° W.; desc. 30 ft. over rocky SW. slope.
- 79.98 The cor. of secs. 19, 20, 29, and 30.  
 Land, broken, hilly to mountainous.  
 Soil, rocky and gravelly loam, 3rd and 4th rate.  
 Undergrowth, creosote and cacti.  
 No timber.
- 
- West, on true line bet. secs. 19 and 30.
- Asc. gentle SE. slope, through dense undergrowth.
- 83.00 Low saddle in spur ridge, bears SW. and NE.; desc. gentle W. slope.
- 86.20 Broad flat head of draw, drains N. 20° W.; asc. 130 ft. over broken NE. slope.
- 95.00 Small spur, projects N.; desc. 100 ft. over W. slope.
- 103.00 Dry wash, 20 lks. wide, 4 ft. deep at foot of slope, drains N., continue over gentle N. slope.
- 114.00 Set an iron post, 3 ft. long, 1 in. diam., 18 ins. in the ground, to solid rock with a limestone 8x6x4 ins., marked with a cross (X), deposited at base, and in a large mound of stone, for  $\frac{1}{4}$  sec. cor., with brass cap mkd.
- $\frac{1}{4}$  S19  
 $\frac{1}{4}$  S30  
 1933
- 122.50 Small water channel, drains N. 70° E.
- 135.80 Broad, shallow water channel, forming the main drainage from the SW., course NE.
- 149.75 Intersect W. bdy. of Tp. S., 4.10 chs. dist. from the cor. of secs. 24 and 25, which is an iron post 3 ins. diam., marked and witnessed, as heretofore described.  
 At point of intersection,  
 Set an iron post 3 ft. long, 3 ins. diam., 6 ins. in the ground to solid rock, over a cross (X) cut in solid rock at exact cor. point and in a large mound of stone for the closing cor. of secs. 19 and 30, with brass cap mkd.