

## SOUTH BOUNDARY OF T.22 S.,R.65 E.

## Chains

55.46 Intersect the mean high water mark on the right bank of the Colorado River; also true point for the meander cor. of secs. 6 and 31. Impracticable to establish cor. at this point.

Land, gently rolling and broken with a general E. exposure and drainage.

Soil, sandy, gravelly and rocky of volcanic and conglomerate formation; 2nd. to 4th. rates.

No timber.

Undergrowth, creosote, black brush and mesquite.

## SOUTH BOUNDARY OF T.22 S.,R.65 E.

From the reconstructed original cor. of Tps. 22 and 23 S.,Rs. 64 and 65 E., heretofore described.

East, bet. secs. 6 and 31.

Descend abruptly E. slope over rough and broken mountainous land through scattered undergrowth.

3.40 Begin precipitous descent over ledges, bears N. and S.

14.50 Gulch, 405 ft. below Tp. cor., drains NE.; abrupt ascent over W. slope.

27.50 Spur, 165 ft. above gulch, projects N.; descend abruptly E. slope over ledges and boulders.

38.30 Draw, 255 ft. below spur, drains N.; ascend W. slope.

40.00 On steep N. slope.

Set an iron post, 3 ft. long, 1 in. in dia., 6 ins. in the ground on solid rock and in a large mound of stone for  $\frac{1}{4}$  sec. cor., with brass cap marked

$\frac{1}{4}$  — S31

1930

Deposit a volcanic rock, 8x6x4 ins., marked with a cross (+) on one face at base of post.

48.54 Spur, 205 ft. above draw, projects N.; gradually descend.