

INDEPENDENT RESURVEY OF SUBDIVISION, T. 21 S., R. 65 E.

Chains

79.70 Low spur, 50 ft. above draw, projects S. 10° E. from NW.; descend gradual N. slope.

79.90 The cor. of secs. 4, 5, 8, and 9, 10 ft. below spur.

Land, rough and broken, with a general south and southeast exposure and drainage.

Soil, shallow gravel, clay, sand, and rock; black volcanic formation; 3rd rate.

Undergrowth, creosote, shadscale, and greasewood.

No timber.

N. 0°01' E., bet. secs. 4 and 5.

Descend gradually along rolling E. slope of broken land, through scattered undergrowth.

1.30 Head of small draw, 15 ft. below cor., drains N. 80° E.; ascend gradually along E. slope.

15.50 Top of rise on E. slope, 90 ft. above draw, bears E. and W.; descend gradual NE. slope.

26.20 Large draw, 85 ft. below top of rise, drains SE.; ascend abrupt S. slope.

35.28 Intersect the fifth standard parallel south, R. 65 E., East, 28.40 chs. dist. from the standard cor. of secs. 32 and 33, which is an iron post, 2 ins. diam., firmly set, marked and witnessed as described in the official records, book "A" of this group.

At point of intersection; on S. slope, 135 ft. above draw.

Set an iron post, 3 ft. long, 2 ins. diam., 12 ins. in the ground to bedrock and in a mound of stone to top, for closing cor. of secs. 4 and 5, with brass cap marked

T20S R65E

S33

S5

S4

T21S

R65E

C

1931

raise a mound of stone, 3 ft. base, 2 ft. high, S. of cor.

Land, rough and broken, with a general southeasterly exposure and drainage.

Soil, clay, and sandy with rock; black volcanic formation; 3rd rate.

Undergrowth, shadscale and creosote.

No timber