

SURVEY OF A PORTION OF THE W. BDY. OF T. 16 N., R. 45 $\frac{1}{2}$ E. 301

Chains
40.00

Set an iron post, 3 ft. long, 1 in. diam., 27 ins. in the ground, for $\frac{1}{4}$ sec. cor. of sec. 35 only; with brass cap mkd.

$\frac{1}{4}$ S 35

1937

from which

A pinon pine, 3 ins. diam., bears N. $34\frac{1}{2}^{\circ}$ E., 50 lks. dist., mkd. BT only.

A pinon pine, 10 ins. diam., bears S. $67\frac{1}{2}^{\circ}$ E., 11 lks. dist., mkd. $\frac{1}{4}$ S 35 BT.

Continue along an irregular E. slope.

50.60

Drain, course NE.

63.80

Drain, course E., desc. 100 ft. over a broken E. slope.

80.00

Set an iron post, 3 ft. long, 2 ins. diam., 27 ins. in the ground, for cor. of secs. 26 and 35 only, with brass cap mkd.

T16N

R45 $\frac{1}{2}$ E

S 26

S 35

1937

from which

A juniper, 7 ins. diam., bears N. $49\frac{1}{2}^{\circ}$ E., 96 lks. dist., mkd. T16N R45 $\frac{1}{2}$ E S26 BT.

A pinon pine, 12 ins. diam., bears S. $77\frac{1}{2}^{\circ}$ E., 105 lks. dist., mkd. T16N R45 $\frac{1}{2}$ E S35 BT.

Land, mountainous.

Soil, rocky clay loam; 3rd rate.

Undergrowth, sagebrush, buckbrush.

Timber, pinon pine, juniper.

Grazing, poor to fair.

North, along the W. bdy. of sec. 26.

Over rolling mountainous land thru scattering small timber and scattering undergrowth. Desc. 240 ft. over an irregular NE. slope.

16.60

Watercourse in large draw, drains N. 40° W., continue over rolling land.

21.80

Old wood road, bears N. 50° W. and S. 30° E.

25.40

Intersect the Standard SE. cor. of, T. 16 N., R. 45 E., which is an iron post, 3 ins. diam., firmly set, mkd. and witnessed as described in the field notes of T. 16 N., R. 45 E., surveyed under this group.

Note: The remainder of the W. bdy. of T. 16 N., R. 45 $\frac{1}{2}$ E., is a common boundary with the east bdy. of T. 16 N., R. 45 E., the detailed record is found in the field notes above mentioned. Quarter section and closing section corners referring to R. 45 $\frac{1}{2}$ E. only are described in connection with the subdivisional record of this township.

Land, rolling and hilly.

Soil, rocky clay loam; 2nd and 3rd rate.