, \$ (9.g)

	٠, ٠٠ ج٠	INDEPENDENT RESURVEY OF THE EAST BDY. OF T. 19 N., R. 50 F
	Chains	North, bet. secs. 7 and 12.
	,	Over level valley floor, through medium dense undergrowth
	.30	Main dirt road, bears N. 15° E. to U. S. Highway No. 50 and S. 15° W. to Antelope Valley.
-	19.10	Unimproved road, bears N. 80° E. and S. 80° W.
٥	30:80	Shallow dry wash, drains N. 40° E. Overflow water from Bartine's Ranch, a stream about 5 lks. wide and 4" deep, drains down this wash at intermittent periods.
	35.70	Shallow, dry wash, drains NE.
	40.00	Set an iron post, 3 ft. long, 1 in. diam., 30 ins. in the ground, for 4 sec. cor., with brass cap mkd.
	.322J	S12 S7
		Deposit a quart of broken glass at base of post.
	Marine Marine Marine	From this cor., U.S.G.S.B.M. "R-36-1931", bears N. 67°30' E., 33.51 chs. dist.
	40.90	Center line of dirt drainage dyke of highway, bears N. 63° E. and S. 63° W.
	44.31	Center line of U.S. Highway No. 50, oil surfaced, bears N. 71°17' E. to Eureka and S. 71°17' W. to Austin.
	70.70	Old stage road, Austin to Eureka, unimproved, bears N. 85° E. and S. 85° W.
	80.00	Set an iron post, 3 ft. long, 2 ins. diam., 30 ins. in the ground, for cor. of secs. 1, 6, 7, and 12, with brass cap mkd.
		T19N R50E R51E S1 S6
		S12 S7
		1936
		Deposit a quart of broken glass at base of post.
		Land, level valley floor. Soil, sandy to gravelly; 2nd rate. Undergrowth, black sage. Timber, none. Grazing, poor.
	-1000	
	ar . T .	North, bet. secs. 1 and 6.
	- 1 of	Over rolling valley floor, through medium dense under- growth.
	8.00	Wide, shallow wash, drains N. 85° E.
		an (70 %) june 1 minung valendari 1 maa 1 minung
	61	