COMPLETION OF THE SUBDIVISION OF T. 14 N., R. 28 E.

Chains 61.70	Ravine, course W.
63.49	Small spur, slopes W.
73.10	Old dirt road, bears S. 30° W. and NE.
78.60	Draw, drains W.
80.00	Set an iron post, 3 ft. long, 2 ins. diam., 30 ins. in the ground, for cor. of secs. 11, 12, 13 and 14, with brass cap mkd.
	T14N R28E S11 S12 S11 S13
to a la .	\$14 \$13 1937
	of stone, 4 ft. base, 3 ft. high, W. of cor.
0 100	Land, rolling hills. Soil, sandy loam and gravel, 4th rate. No timber; undergrowth, shadscale and button sage.
	Grazing, poor.
	S. 89°41' E. on random line, bet. secs. 12 and 13.
40.00	Set temp. 1 sec. cor.
79.92	Intersect E. bdy. of Tp. 9 lks. S. of cor. of secs. 7, 12, 13 and 18, a 2 in. iron post, 3 ft. long, firmly set, mkd. and witnessed as described in the field notes of T. 14 N., R. 29 E., recorded in
	book "0" and executed under this group.
	book "O" and executed under this group.
g* *0 a s r	book "O" and executed under this group. Thence
4.80	book "O" and executed under this group. Thence N. 89° 45' W. on true line, bet. secs. 12 and 13. Over broken land through medium dense undergrowth, asc. over a broken NE. slope, 130 ft. Gallis's frame house bears N. 40° 43' E., continue along N. slope of spur.
4.80 17.60	book "O" and executed under this group. Thence N. 89° 45' W. on true line, bet. secs. 12 and 13. Over broken land through medium dense undergrowth, asc. over a broken NE. slope, 130 ft. Gallis's frame house bears N. 40° 43' E., continue along N. slope of spur. S. edge of saddle, spur slopes S. 10° E.
	book "0" and executed under this group. Thence N. 89° 45' W. on true line, bet. secs. 12 and 13. Over broken land through medium dense undergrowth, asc. over a broken NE. slope, 130 ft. Gallis's frame house bears N. 40° 43' E., continue along N. slope of spur.
	book "O" and executed under this group. Thence N. 89° 45' W. on true line, bet. secs. 12 and 13. Over broken land through medium dense undergrowth, asc. over a broken NE. slope, 130 ft. Gallis's frame house bears N. 40° 43' E., continue along N. slope of spur. S. edge of saddle, spur slopes S. 10° E. From this point Gallis's frame house bears N. 53° 28' E.; a prom-
17.60	book "0" and executed under this group. Thence N. 89° 45' W. on true line, bet. secs. 12 and 13. Over broken land through medium dense undergrowth, asc. over a broken NE. slope, 130 ft. Gallis's frame house bears N. 40° 43' E., continue along N. slope of spur. S. edge of saddle, spur slopes S. 10° E. From this point Gallis's frame house bears N. 53° 28' E.; a prominent peak bears S. 63° 15' W.
17.60	Thence N. 89° 45' W. on true line, bet. secs. 12 and 13. Over broken land through medium dense undergrowth, asc. over a broken NE. slope, 130 ft. Gallis's frame house bears N. 40° 43' E., continue along N. slope of spur. S. edge of saddle, spur slopes S. 10° E. From this point Gallis's frame house bears N. 53° 28' E.; a prominent peak bears S. 63° 15' W. Head of ravine, course S.
17.60 19.60 22.60	book "O" and executed under this group. Thence N. 89° 45' W. on true line, bet. secs. 12 and 13. Over broken land through medium dense undergrowth, asc. over a broken NE. slope, 130 ft. Gallis's frame house bears N. 40° 43' E., continue along N. slope of spur. S. edge of saddle, spur slopes S. 10° E. From this point Gallis's frame house bears N. 53° 28' E.; a prominent peak bears S. 63° 15' W. Head of ravine, course S. Small spur, slopes S.; continue along rolling S. slope.
17.60 19.60 22.60 32.60	book "0" and executed under this group. Thence N. 89° 45' W. on true line, bet. secs. 12 and 13. Over broken land through medium dense undergrowth, asc. over a broken NE. slope, 130 ft. Gallis's frame house bears N. 40° 43' E., continue along N. slope of spur. S. edge of saddle, spur slopes S. 10° E. From this point Gallis's frame house bears N. 53° 28' E.; a prominent peak bears S. 63° 15' W. Head of ravine, course S. Small spur, slopes S.; continue along rolling S. slope. Graded wagon road to miner's cabin, bears S. and NW. down ravine. SW. cor. of small cabin bears N. 10° 43' W. Set an iron post, 3 ft. long, 1 in. diam., 18 ins. in the ground to solid rock and in a mound of stone to top, for ½ sec. cor., with brass cap mkd.
17.60 19.60 22.60 32.60 38.10	book "0" and executed under this group. Thence N. 89° 45' W. on true line, bet. secs. 12 and 13. Over broken land through medium dense undergrowth, asc. over a broken NE. slope, 130 ft. Gallis's frame house bears N. 40° 43' E., continue along N. slope of spur. S. edge of saddle, spur slopes S. 10° E. From this point Gallis's frame house bears N. 53° 28' E.; a prominent peak bears S. 63° 15' W. Head of ravine, course S. Small spur, slopes S.; continue along rolling S. slope. Graded wagon road to miner's cabin, bears S. and NW. down ravine. SW. cor. of small cabin bears N. 10° 43' W. Set an iron post, 3 ft. long, 1 in. diam., 18 ins. in the ground to solid rock and in a mound of stone to top, for ½ sec. cor., with brass cap mkd.
17.60 19.60 22.60 32.60 38.10	Thence N. 89° 45' W. on true line, bet. secs. 12 and 13. Over broken land through medium dense undergrowth, asc. over a broken NE. slope, 130 ft. Gallis's frame house bears N. 40° 43' E., continue along N. slope of spur. S. edge of saddle, spur slopes S. 10° E. From this point Gallis's frame house bears N. 53° 28' E.; a prominent peak bears S. 63° 15' W. Head of ravine, course S. Small spur, slopes S.; continue along rolling S. slope. Graded wagon road to miner's cabin, bears S. and NW. down ravine. SW. cor. of small cabin bears N. 10° 43' W. Set an iron post, 3 ft. long, 1 in. diam., 18 ins. in the ground to solid rock and in a mound of stone to top, for ½ sec. cor., with brass cap mkd.
17.60 19.60 22.60 32.60 38.10	book "0" and executed under this group. Thence N. 89° 45' W. on true line, bet. secs. 12 and 13. Over broken land through medium dense undergrowth, asc. over a broken NE. slope, 130 ft. Gallis's frame house bears N. 40° 43' E., continue along N. slope of spur. S. edge of saddle, spur slopes S. 10° E. From this point Gallis's frame house bears N. 53° 28' E.; a prominent peak bears S. 63° 15' W. Head of ravine, course S. Small spur, slopes S.; continue along rolling S. slope. Graded wagon road to miner's cabin, bears S. and NW. down ravine. SW. cor. of small cabin bears N. 10° 43' W. Set an iron post, 3 ft. long, 1 in. diam., 18 ins. in the ground to solid rock and in a mound of stone to top, for ½ sec. cor., with brass cap mkd.
17.60 19.60 22.60 32.60 38.10 39.96	Thence N. 89° 45' W. on true line, bet. secs. 12 and 13. Over broken land through medium dense undergrowth, asc. over a broken NE. slope, 130 ft. Gallis's frame house bears N. 40° 43' E., continue along N. slope of spur. S. edge of saddle, spur slopes S. 10° E. From this point Gallis's frame house bears N. 53° 28' E.; a prominent peak bears S. 63° 15' W. Head of ravine, course S. Small spur, slopes S.; continue along rolling S. slope. Graded wagon road to miner's cabin, bears S. and NW. down ravine. SW. cor. of small cabin bears N. 10° 43' W. Set an iron post, 3 ft. long, 1 in. diam., 18 ins. in the ground to solid rock and in a mound of stone to top, for ½ sec. cor., with brass cap mkd. S 12 14 S 13