

DEPENDENT RESURVEY OF PORTION OF E. BDY. T. 12 N., R. 29 E.

Chains

Set an iron post, 3 ft. long, 2 ins. diam., 30 ins. in the ground, for cor. of secs. 25, 30, 31, and 36, with brass cap mkd.

T12N
R29E R30E
S25 S30
—+—
S36 S31
1936

Deposit a qt. of charcoal at base of post.

Land, rolling foothills.

Soil, sandy to rocky; 4th rate.

Undergrowth, greasewood, rabbit brush and shadscale.

Timber, none.

Grazing, poor.

N. 0°10' E., on true line bet. secs. 25 and 30.

Over rolling land, through medium dense undergrowth; continue along gentle W. slope of foothills.

4.50 Dry wash, 25 lks. wide, 8 ft. deep, drains NW. 1 ch., thence S. 60° W.

25.60 Dry wash, 30 lks. wide, 6 ft. deep, drains W.

39.92 The orig. $\frac{1}{4}$ sec. cor. of secs. 25 and 30, which is a redwood post, 3 ins. sq., 20 ins. above ground, firmly set, properly mkd. and witnessed, as described in the official record.

Alongside of old post,

Set an iron post, 3 ft. long, 1 in. diam., 30 ins. in the ground, for $\frac{1}{4}$ sec. cor., with brass cap mkd.

$\frac{1}{4}$
S25 S30
—+—
1936

Deposit a qt. of broken glass at base of post.

Land, rolling.

Soil, sandy to gravelly; 3rd rate.

Undergrowth, greasewood and shadscale.

Timber, none.

Grazing, fair.

DEPENDENT RESURVEY OF A PORTION OF THE SUBDIVISION OF
T. 12 N., R. 29 E.

REESTABLISHMENT OF A PORTION OF THE SURVEYS EXECUTED BY
J. E. FRANKS AND J. S. MULLEN, U.S. DEPUTY SURVEYORS,
IN 1904
CONTRACT NO. 237

Random Lines

Beginning at the remonumented original cor. of secs. 25,