

## DEPENDENT RESURVEY OF PORTION OF SUBDIVISION T. 12 N., R. 29 E.

Chains

N. 80° W. to Schurz, Nevada.

79.27

The cor. of secs. 3, 4, 33, and 34 on the N. bdy. of the Tp., which is an iron post, 2 ins. diam., firmly set, properly mkd. and witnessed, as described in the official record.

Land, rolling.  
Soil, sandy; 3rd rate.  
Undergrowth, greasewood and shadscale.  
Timber, none.  
Grazing, fair.

COMPLETION OF THE SURVEY OF THE EAST BOUNDARY  
OF T. 12 N., R. 29 E.

Beginning at the remonumented original  $\frac{1}{4}$  sec. cor. of secs. 25 and 30, on the E. bdy. of the Tp., heretofore described.

North, on a random line, setting temporary  $\frac{1}{4}$  sec. and sec. corners at intervals of 40.00 chs. along the range line in T. 12 N., bet. Rs. 29 and 30 E. At 359.10 chs., intersect the S. bdy. of T. 13 N., R. 29 E., West, 1.58 chs. dist. from the cor. of Tps. 12 and 13 N., Rs. 29 and 30 E., hereinafter described. The correction to true line is  $17\frac{1}{2}$  lks. E. per  $\frac{1}{2}$  mile, counting from the  $\frac{1}{4}$  sec. cor. of secs. 25 and 30. The true course is, therefore, N. 0°15' E.

Thence,

N. 0°15' E., on true line bet. secs. 25 and 30.

Over gently rolling land, through medium dense undergrowth; along a general W. slope.

28.80

Dry wash, 8 lks. wide, 3 ft. deep, drains N. 80° W.

40.00

Set an iron post, 3 ft. long, 2 ins. diam., 30 ins. in the ground, for cor. of secs. 19, 24, 25, and 30, with brass cap mkd.

T12N  
R29E R30E  
S24 S19  
S25 S30  
1936

Deposit broken glass at base of post.

Land, rolling.  
Soil, sandy to gravelly; 3rd rate.  
Undergrowth, greasewood and shadscale.  
Timber, none.  
Grazing, fair.

N. 0°15' E., on true line bet. secs. 19 and 24.

Over gently rolling land, through medium dense undergrowth; along gentle W. slope.