

-11-

DEPENDENT RESURVEY OF A PORTION OF THE SUBDIVISION OF
T. 13 N., R. 29 E.

Chains

North, on true line between secs. 1 and 6.

Over gently rolling foothills; asc. 80 ft. to $\frac{1}{4}$ sec. cor.
over a gentle S. slope.

39.96

The original $\frac{1}{4}$ sec. cor., which is a redwood post, 4 ins.
sq., 12 ins. above ground, firmly set, properly marked and
witnessed, as described in the official record.

Alongside of old post,

Set an iron post, 3 ft. long, 1 in. diam., 30 ins. in the
ground, for $\frac{1}{4}$ sec. cor., with brass cap mkd.
$$\begin{array}{c} \frac{1}{4} \\ S1 \quad | \quad S6 \\ 1936 \end{array}$$

Deposit a quart of broken glass at base of post.

N. 0° 07' E., on true line with continuous measurement.

Asc. 74 ft. over gentle S. slope.

55.90

Low spur, projects W.

Desc. 34 ft. over gentle N. slope.

60.70

Draw, drains W.; asc. 90 ft. over gradual S. slope.

79.96

The original cor. of Tps. 13 and 14 N., Rs. 28 and 29 E.,
which is a granite rock, 15 x 15 x 16 ins. above ground,
firmly set, properly marked and witnessed as described in
the official record.

Alongside of corner,

Set an iron post, 3 ft. long., 3 ins. diam., 30 ins. in
the ground, for cor. of Tps. 13 and 14 N., Rs. 28 and 29 E.,
with brass cap mkd.
$$\begin{array}{c} T14N \\ R28E \quad R29E \\ S36 \quad S31 \\ + \\ S1 \quad S6 \\ T13N \\ 1936 \end{array}$$

Deposit a quart of broken glass at base of post.

Land, rolling.

Soil, gravelly to rocky; 4th rate.

Undergrowth, greasewood and shadscale.

Timber; none.

Grazing, poor.

DEPENDENT RESURVEY OF A PORTION OF THE SUBDIVISION
OF T. 13 N., R. 29 E.