

SUBDIVISION OF T. 11 N., R. 30 E.

Chains

ground to underlying rock, with a basalt rock, 6x4x4 ins., mkd. X, deposited at the base, and in a large mound of stone to top of post, for cor. of secs. 13, 14, 23, and 24, with brass cap mkd.

T11N R30E

S14 | S13

S23 | S24

1937

Land, rolling and hilly.

Soil, shallow gravelly to rocky loam, 3rd rate.

Undergrowth, shadscale, rabbit brush.

No timber.

Grazing, good.

N. 89° 55' E., on a random line bet. secs. 13 and 24,

40.00 Set temp. $\frac{1}{4}$ sec. cor.,

80.12 Intersect E. bdy. of Tp. 3 lks. S. of the cor. of secs. 13, 18, 19, and 24, which is an iron post, 2 ins. diam., firmly set, mkd. and witnessed as described in the field notes of T. 11 N., R. 31 E.

Thence

S. 89° 54' W., on true line bet. secs. 13 and 24.

Over rolling hilly land thru medium dense low undergrowth.

6.40 Divide, bears NE. and S. 70° W., continue over broken N. slope.

14.40 Hillside drain, course NW.

23.40 Head of draw, drains N., continue along broken N. slope.

40.06 Set an iron post, 3 ft. long, 1 in. diam., 27 ins. in the ground, for $\frac{1}{4}$ sec. cor., with brass cap mkd.

S 13

S 24

1937

of stone, 3 ft. base, 2 ft. high, N. of cor. raise a mound

41.30 Hillside drain, course NW.

47.30 Old road bears N. and S. in bottom of draw draining N.

55.50 Small draw, drains N.

61.30 Hillside drain, course NE.

66.80 Spur slopes SE. from W., asc. along top of spur.

77.60 Same spur, slopes E. from N. 60° W., continue along SW. slope.

79.50 Hillside drain, course S. 20° W.

80.12 The cor. of secs. 13, 14, 23, and 24.

-Land, rolling hilly.

Soil, coarse gravelly to rocky loam, 3rd rate.

Undergrowth, shadscale, greasewood, rabbit brush.