

## SUBDIVISION OF T. 11 N., R. 30 E.

Chains

S 18
7   8
—
2   1
S 19
1938

Deposit a granite rock, 9x6x5 ins., mkd. X, at base of post.

- 83.10 Spur, slopes N. 80° W.  
 92.20 Draw, drains S. 30° W., asc. along S. slope.  
 100.30 Spur, slopes S. 60° W.  
 100.84 Intersect W. bdy. of Tp.

Set an iron post, 3 ft. long, 2 ins. diam., 30 ins. in the ground, for closing cor. of secs. 18 and 19, with brass cap mkd.

T11N
T11N R30E
R29E   S 18
S 24   — CC.
S 19
1938

raise a mound  
of stone, 3 ft. base, 1½ ft. high, E. of cor.

From point of intersection, the old cor. of secs. 13, 18, 19, and 24, T. 11 N., Rs. 29 and 30 E., bears N. 3.85 chs. dist., an iron post, 2 ins. diam., firmly set, mkd. and witnessed as described in the official record. As this cor. will hereafter refer only to R. 29 E., I alter the brass cap markings to read as follows:

T11N
R29E R30E
S 13   S 18 ✓
—
S 24
1918

Land, mountainous and broken hilly.  
 Soil, fine gravelly to coarse loam, 3rd rate.  
 Undergrowth, shadscale, greasewood.  
 No timber.  
 Grazing, fair to good.

From the cor. of secs. 17, 18, 19, and 20,

N. 0° 03' W., bet. secs. 17 and 18,

Over broken mountainous land thru scattering low undergrowth. Asc. 60 ft. over SW. slope.

- 6.10 Spur, slopes W., desc. 140 ft. over NW. slope.  
 10.40 Draw, drains W.  
 13.30 Draw, drains S. 70° W., asc. 130 ft. over S. slope.  
 22.40 Spur, slopes S. 60° W., desc. 120 ft. over NW. slope.