

SUBDIVISION OF T. 13 N., R. 31 $\frac{1}{2}$  E.

## Chains

Undergrowth, shadscale, greasewood.  
No timber.  
Grazing, fair to poor.

East, on a random line, bet. secs. 25 and 36.

40.00 Set temp.  $\frac{1}{4}$  sec. cor.,

79.98 Intersect the E. bdy. of the Tp., 5 lks. N. of the cor. of secs. 25 and 36 which is an iron post, 2 ins. diam., mkd. and witnessed as described in the field notes of T. 13 N., R. 32 E., surveyed under this group.

Thence

N. 89° 58' W., on true line, bet. secs. 25 and 36,

Over broken mountainous land thru scattering low undergrowth; desc. 40 ft. over steep, rocky SW. slope.

6.20 Broad draw, drains SE., continue over broken SE. slope.

22.50 Broad draw, drains S. 80° E., asc. 120 ft. over broken NE. slope.

39.10 Short rocky spur from the South, slopes NE., desc. 30 ft. over NW. slope.

39.99 Set an iron post, 3 ft. long, 1 in. diam., 30 ins. in the ground, for  $\frac{1}{4}$  sec. cor.; with brass cap mkd.

S 25

$\frac{1}{4}$   
S 36

1936

Deposit broken glass at base of post.

43.90 Draw, drains N. 60° E., asc. 70 ft. over broken NE. slope.

53.40 Head of draw, drains N. 80° E., asc. 270 ft. over rough, broken NE. slope.

79.98 The cor. of secs. 25, 26, 35, and 36.

Land, broken hilly to rough mountainous.

Soil, coarse rocky loam, 3d rate.

Undergrowth, shadscale, greasewood.

No timber.

Grazing poor.

West, on a random line, bet. secs. 26 and 35,

40.00 Set temp.  $\frac{1}{4}$  sec. cor.

62.45 Intersect W. bdy. of Tp., 5 lks. S. of the cor. of secs. 25, 26, 35 and 36, which is an iron post, 2 ins. diam., firmly set, mkd. and witnessed as described in the field notes of T. 13 N., R. 31 E. surveyed under this group.

Thence

S. 89° 57' E., on true line, bet. secs. 26 and 35,

Over rough mountainous land thru medium dense low undergrowth, Asc. 180 ft. over broken NW. slopes.