

247

SUBDIVISION OF T. 13 N., R. 31½ E.

Chains	N. 89° 56' W., on a random line, bet. secs. 2 and 11.
40.00	Set temp. $\frac{1}{4}$ sec. cor.,
62.32	Intersect the W. bdy. of Tp., 7 lks. N. of the cor. of secs. 1, 2, 11, and 12, which is an iron post, 2 ins. diam., firmly set, mkd. and witnessed as described in the field notes of T. 13 N., R. 31 E., surveyed under this group.
	Thence
	East, on true line, bet. secs. 2 and 11,
	Over broken hilly land thru medium dense low undergrowth; desc. 140 ft. over abrupt NE. slope.
3.80	Draw, drains N., asc. 140 ft. over steep, rocky W. slope.
8.50	Spur, slopes N. 20° W. from SE., desc. 110 ft. over E. slope.
17.20	Draw, drains N., asc. 120 ft. over NW. slope.
22.32	On spur sloping N. 30° W.,
	Set an iron post, 3 ft. long, 1 in. diam., 12 ins. in the ground to underlying rock, with basalt rock, 4x4x6 ins., mkd. X, deposited at base, and in a large mound of stone to top, for $\frac{1}{4}$ sec. cor., with brass cap mkd.
	S 2
	$\frac{1}{4}$
	S 11
	1937
	Continue along steep N. slope.
25.30	Head of draw, drains N. 30° W.
29.40	Spur, slopes N. 30° W., desc. 150 ft. over E. slope.
36.20	Draw, drains N. 20° E., continue over broken N. slope.
43.90	Spur, slopes S. 70° W. from S. 60° E.
51.20	Draw, drains N. from SE.
57.60	Spur, slopes N. 70° W.
62.32	The cor. of secs. 1, 2, 11, and 12.
	Land, hilly.
	Soil, coarse, rocky loam, 3rd rate.
	Undergrowth, shadscale, sagebrush, greasewood.
	No timber.
	Grazing, fair to good.
	N. 0° 01' W., on a random line, bet. secs. 1 and 2,
40.00	Set temp. $\frac{1}{4}$ sec. cor.,
80.06	Intersect the N. bdy. of Tp., 7 lks. W. of the cor. of secs. 1, 2, 35, and 36, which is an iron post, 2 ins. diam., firmly set, mkd. and witnessed as described in the field notes of T. 14 N., R. 31½ E., surveyed under this group.
	Thence