

SUBDIVISION OF TP. 11 N., R. 32 E.

Chains
80.02

The cor. of secs. 2, 3, 10, and 11.

Land, gentle E. slope, rolling.

Soil, sandy; 3rd rate.

Undergrowth, sage.

Timber, none.

Grazing, poor.

N.0°01'W., on true line bet. secs. 2 and 3.

Along gentle E. slope, thru medium dense undergrowth.
Desc. 80 ft. to closing cor.

16.00

Slope changes to NE.

40.00

Set an iron post, 3 ft. long, 1 in. diam., 27 ins. in the
ground, for the $\frac{1}{4}$ sec. cor., with brass cap mkd.
$$\begin{array}{c} \frac{1}{4} \\ S\ 3 \mid S\ 2 \\ 1936 \end{array}$$
of stone, $3\frac{1}{2}$ ft. base, 3 ft. high, W. of cor. raise a mound

Continue over NE. slope.

68.22

Intersect the N. bdy. of the Tp.

Set an iron post, 3 ft. long, 2 ins. diam., 27 ins. in the
ground, for the closing cor. of secs. 2 and 3, Tp. 11 N.,
R. 32 E., with brass cap mkd.

T12N R32E

$$\begin{array}{c} S35 \\ S\ 3 \mid S\ 2 \\ CC \end{array}$$

T11N R32E

1936

Deposit broken glass at base of post.

From point of intersection, the cor. of secs. 34 and 35,
Tp. 12 N., R. 32 E., an iron post, 2 ins. diam., mkd. and
witnessed as described in the official record, bears West,
3.80 chs. dist.

Land, S. 16 chs., gentle E. slope; balance, gentle NE. slope.

Soil, sandy, gravelly; 3rd rate.

Undergrowth, sage.

Timber, none.

Grazing, poor.

From the cor. of secs. 27, 28, 33, and 34, heretofore
described.

N.0°02'W., bet. secs. 27 and 28.

Over rolling hills, thru scattering undergrowth.

Along broken E. slope; desc. 50 ft. to 5.70 ch. pt.