

SUBDIVISIONS, T. 13 N., R. 32 E.

414

Chains

Land, rolling mountainous.
Soil, rocky, gravelly clay, 3d rate.
Timber, none; undergrowth, sagebrush.
Grazing, poor.

From the cor. of secs. 3, 4, 33 and 34, on the S. bdy. of the Tp.; an iron post, 2 ins. diam., 8 ins. above the ground, mkd. and witnessed, as described in the field notes of the survey of T. 12 N., R. 32 E., surveyed under this group.

N. 0° 02' W., bet. secs. 33 and 34.

Over nearly level, washed land, thru medium dense undergrowth.

12.90 Wash, course S. 50° E.

17.70 Wash, course E.

30.70 Wash, course S. 60° E.

40.00 Set an iron post, 3 ft. long, 1 in. diam., 30 ins. in the ground, with a quart of glass deposited at base, for the $\frac{1}{4}$ sec. cor., with brass cap mkd.

$\frac{1}{4}$
 S33 | S34
 1936

44.10 Wash, course S. 65° E.

48.90 Wash, course E.

64.00 Wash, course SE.

72.00 Wash, course S. 70° E.

80.00 Set an iron post, 3 ft. long, 2 ins. diam., 30 ins. in the ground, with a quart of glass deposited at base, for the cor. of secs. 27, 28, 33, and 34, with brass cap mkd.

T13N R32E
 S28 | S27
 S33 | S34
 1936

Land, nearly level.
Soil, sandy, rocky clay, 3d rate.
Timber, none; undergrowth, sagebrush.
Grazing, poor.

East on a random line, bet. secs. 27 and 34.

40.00 Set temp. $\frac{1}{4}$ sec. cor.

80.06 Intersect the N. and S. line at the cor. of secs. 26, 27, 34 and 35.

Thence

West, on true line, bet. secs. 27 and 34.

Over nearly level land, thru medium dense undergrowth.