

INDEPENDENT RESURVEY OF THE S. BDY. OF T. 12 N., R. 32 E.

Chains	
	Set an iron post, 3 ft. long, 1 in. diam., 30 ins. in the ground, for $\frac{1}{4}$ sec. cor. of sec. 32 only, with brass cap mkd.
	$\frac{1}{4}$ S32
	1936
	Deposit broken glass at base of post.
80.00	N. 20 lks. from the tangent, Set an iron post, 3 ft. long, 2 ins. diam., 30 ins. in the ground, for cor. of secs. 31 and 32 only, with brass cap mkd.
	T12NR32E S31 S32
	S6 T11N 1936
	Deposit broken glass at base of post.
	Land, rolling. Undergrowth, shadscale. Soil, sandy to rocky; 3rd rate. Timber, none. Grazing, poor.
	West, along S. bdy. of sec. 31, on a transit line describing the tangent, which bears S. 89° 56.5' W.
	Over rolling foothills, through medium dense undergrowth.
8.00	Asc. gradual NE. slope.
9.40	Wash, drains N. 70° E.
25.90	Center of wash, 1 ch. wide and 5 ft. deep; drains N. 60° E.
40.00	N. 25 lks. from the tangent, Set an iron post, 3 ft. long, 1 in. diam., 30 ins. in the ground, for $\frac{1}{4}$ sec. cor. of sec. 31 only, with brass cap mkd.
	$\frac{1}{4}$ S31
	1936
	Deposit broken glass at base of post.
42.50	Head of wash, draining NE. at base of mountain, bearing NW. and S.; asc. 200 ft. to 67.80 ch. pt.; asc. over SE. slope.
57.80	Wash, drains N. 30° E.; slope changes to NE.