

Survey of the Subdivision of T. 19 N., R. 53 E.

Chains

49.40 Large draw, drains N. 20° W.; asc. along a broken N. slope.

61.10 Small spur, slopes N. 30° E.

80.80 Main draw, drains N. 20° E.

81.50 Unimproved road, bears N. 20° E. and S. 20° W.; asc. 70 ft. over E. slope.

84.90 Intersect the E. bdy. of sec. 24, T. 19 N., R. 52 E., at point for closing cor. of secs. 18 and 19.

Set an iron post, 3 ft. long, 2 ins. diam., 27 ins. in the ground, with brass cap mkd.

T19N
R52E R53E
S24 | S18 CC
 | S19
 1937

No auxiliary accessory.

From this corner, the cor. of secs. 13 and 24, T. 19 N., R. 52 E., bears North, 14.80 chs. dist.

Land, broken hilly to mountainous.
Soil, shallow coarse rocky loam.
Timber, juniper, pinon, and scattering scrub mahogany; undergrowth, sagebrush and buckbrush.

At the point for the W. ¼ sec. cor. of sec. 19, at midpoint bet. the NW. and SW. cors. of sec. 19.

Set an iron post, 3 ft. long, 1 in. diam., 30 ins. in the ground, with brass cap mkd.

| ¼
| S 19
1937

Raise a mound of stone, 2 ft. base, 1½ ft. high, E. of cor.

From this corner, the E. ¼ sec. cor. of sec. 24, T. 19 N., R. 52 E., bears North, 14.84 chs. dist.

From the cor. of secs. 17, 18, 19 and 20.

N. 0° 04' W., bet. secs. 17 and 18.

Over broken hilly land, through scattering scrub timber and medium dense undergrowth; desc. 50 ft. over NW. slope.

6.00 Draw, drains N. 60° E.

8.10 Unimproved road, bears N. 60° E. and S. 80° W.; asc. along a broken E. slope.

20.50 Draw, drains SE.; asc. 230 ft. over abrupt, rocky SE. slope.