

Dependent Resurvey of a Portion of the E. Bdy.
T. 11 N., R. 58 E.

Chains

A juniper, 8 ins. diam., bears N. $84\frac{1}{4}^{\circ}$ W., 307 lks. dist.,
mkd. T11N R58E S13 BT.

A juniper, 4 ins. diam., bears S. $17\frac{1}{2}^{\circ}$ W., 208 lks. dist.,
mkd. only S24 BT.

Land, in the south 30 chains is rolling broken mountainous; the
remainder of the mile is rough rugged mountainous.

Soil, generally shallow sand, with decomposed limestone, shale,
porphyry and gravel quartzite near the surface, with indications
of gold bearing quartz outcroppings.

Timber, scrub juniper and a few pinon pine; undergrowth, sagebrush,
greasewood, buckbrush, jointbrush and grass.

Grazing, good.

Mineral indications of gold deposit were observed.

Survey of Portion of the East Boundary of
T. 11 N., R. 58 E.

North, along the E. bdy. of sec. 13.

Over mountainous land, through scattering timber and dense under-
growth; asc. 80 ft. along a broken rocky SW. slope.

- 4.80 Hillside drain, course W.; asc. 180 ft. along SW. slope.
- 16.80 Top of spur ridge, bears S. 55° W. and S. 20° E.; desc. 240 ft. over
a rocky broken N. slope.
- 26.70 Wire fence, bears N. 58° E. and S. 58° W.
- 28.20 Ravine, course S. 35° W.; asc. 75 ft. over a rocky SW. slope.
- 34.70 Ungraded road, bears N. 35° E. and S. 35° W.
- 37.35 Wire fence, bears N. $3\frac{3}{4}^{\circ}$ E. and S. $3\frac{3}{4}^{\circ}$ W.
- 38.03 Intersect line, 1-5 of Homestead Entry Survey No. 189.
- From this point, cor. No. 1-189 HES., bears N. 43° $04'$ W.,
36.6 lks. dist.; a limestone, 6x8x10 ins., firmly set, mkd.
and witnessed as described in the official record.
- 38.65 Intersect line, 1-2 of Homestead Entry Survey No. 189.
- From this point, cor. No. 1-189 HES., bears S. 35° $28'$ W.,
43 lks. dist.
- 40.00 Set an iron post, 3 ft. long, 1 in. diam., 27 ins. in the ground,
for $\frac{1}{4}$ sec. cor. of sec. 13, with brass cap mkd.
- $\frac{1}{4}$ S13 |
1941
- from which
- A forked pinon pine, 12 ins. diam., bears S. $74\frac{3}{4}^{\circ}$ W.;
415 lks. dist., mkd. $\frac{1}{4}$ S13 BT.
- A pinon pine, 8 ins. diam., bears N. $55\frac{3}{4}^{\circ}$ W., 246 lks. dist.,
mkd. $\frac{1}{4}$ S13 BT.
- Ascend 30 ft. along a general SW. slope.
- 44.20 Wash, 10 lks. wide, 2 ft. deep, course S. 10° W.; asc. 170 ft. along
broken SW. slope.