

## Survey of a Portion of the East Boundary of T. 11 N., R. 58 E.

- Chains  
62.20 Top of spur, slopes N. 65° E. for about 15.00 chs.; thence projects E.; desc. 80 ft.  
Leave dense mahogany and continue through dense fir and pinon pine timber.
- 64.70 Top of cliff, bears NE. and SW.; precipitous descent of 50 ft.; thence desc. 480 ft. over series of limestone ledges, crags and outcroppings.
- 74.82 A point, 482.35 chs. West of the cor. of Tps. 12 N., Rs. 59 & 60 E.  
Set an iron post, 3 ft. long, 3 ins. diam., 4 ins. in the ground to bedrock and in a large mound of stone to top, for cor. of Tps. 11 and 12 N., Rs. 58 and 59 E., with brass cap mkd.

T12N	
R58E	R59E
S36	S31
S 1	S 6
T11N	
1941	

from which

A balsam fir, 10 ins. diam., bears N. 76° E., 80 lks. dist., mkd. T12N R59E S31 BT.

A mahogany, 12 ins. diam., bears S. 50° E., 90 lks. dist., mkd. T11N R59E S6 BT.

A balsam fir, 9 ins. diam., bears S. 27° W., 57 lks. dist., mkd. T11N R58E S1 BT.

A balsam fir, 8 ins. diam., bears N. 86° W., 41 lks. dist., mkd. T12N R58E S36 BT.

Land, rough rugged mountainous.

Soil, light fine sandy gravelly and shallow loam, medium texture, moist, on limestone base, with numerous limestone ledges, outcroppings and crags; 4th rate.

Timber, balsam fir, pinon pine, juniper and mahogany.

Undergrowth, sagebrush, laurel, buckbrush, servicebrush and grass. Grazing, good.

## Survey of the South Boundary of T. 12 N., R. 59 E.

Beginning at the cor. of Tps. 12 N., Rs. 59 and 60 E.; which is a limestone, 6x18x24 ins., firmly set in ground, standing 6 ins. above the surface; mkd. with 6 notches on E. edge only.

At the cor. point, with the original stone, deposited at the base,

Set an iron post, 3 ft. long, 3 ins. diam., 12 ins. in the ground to bedrock, and supported in a large mound of stone to top, for cor. of Tps. 12 N., Rs. 59 and 60 E., with brass cap mkd.

T12N	
R59E	R60E
S36	S31
T11N	R60E
S 6	
1941	

from which