

Survey of the South Bdy. of T. 12 N., R. 59 E.

Chains	from which
	A pinon pine, 4 ins. diam., bears N. $38\frac{1}{4}^{\circ}$ W., 30 lks. dist., mkd. $\frac{1}{4}$ S31 BT.
	A pinon pine, 7 ins. diam., bears N. $35\frac{1}{4}^{\circ}$ E., 35 lks. dist., mkd. $\frac{1}{4}$ S31 BT.
	Desc. 65 ft. along rocky SW. slope.
48.80	Head of hillside drain, course S. 60° E.; asc. 470 ft.
67.20	Top of same spur at (38.90) slopes NE.; desc. along a broken cragy N. slope and over series of ledges 50 ft.
79.20	Bottom of descent; thence asc. 45 ft.
80.60	Top of crag, projects N.; desc. abruptly 50 ft.
82.35	N. 29 lks. from the tangent.
	The cor. of Tps. 11 and 12 N., Rs. 58 and 59 E.
	Land, mountainous.
	Soil, shallow sandy clay loam and rocky; 4th rate.
	Timber, pinon pine, juniper, balsam fir, alpine fir, foxtail pine and mahogany.
	Undergrowth, sagebrush, laurel, buckbrush, brierbrush and grass.
	Grazing, good.
Subdivision of T. 11 N., R. 59 E.	
Beginning at the standard cor. of secs. 35 and 36.	
N. 0° 01' W., bet. secs. 35 and 36.	
Over mountainous land, through scattering timber and dense undergrowth, desc. 125 ft. over NW. slope.	
8.00	Ravine, course S. 60° W.; asc. 240 ft. over rocky broken SW. slope.
21.00	Top of spur, projects S. 65° W.; desc. 260 ft. over a densely timbered and broken rocky NW. slope to $\frac{1}{4}$ sec. cor.
40.00	Set an iron post, 3 ft. long, 1 in. diam., 12 ins. in the ground to bedrock and in a mound of stone to top, for $\frac{1}{4}$ sec. cor., with brass cap mkd.
	$\frac{1}{4}$
	S35 S36
	1941
	from which
	A pinon pine, 8 ins. diam., bears N. $66\frac{1}{4}^{\circ}$ E., 48 lks. dist., mkd. $\frac{1}{4}$ S36 BT.
	A pinon pine, 6 ins. diam., bears N. 18° W., 13 lks. dist., mkd. $\frac{1}{4}$ S35 BT.
45.10	Ravine, 135 ft. below $\frac{1}{4}$ sec. cor., course N. 70° W.; asc. 110 ft.