

440

Dependent Resurvey, Portion of the South Boundary, T. 28 N., R. 58 E.

Chains

78.80

The original cor. of secs. 5, 6, 31 and 32, monumented with a partly decayed and weathered cedar post, 3 ft. long, 2 ins. diam., top squared, but markings weathered away. Alongside of this is a firmly set iron pipe, $2\frac{1}{2}$ ins. diam., 8 ins. above ground.

At the corner point

Set an iron post, 3 ft. long, 2 ins. diam., 28 ins. in the ground, with brass cap mkd.

T28N R58E
 S31 | S32
 S6 | S5
 T27N
 1944

Deposit the old cedar post and iron pipe alongside the iron post and raise a mound of stone, 2 ft. base, $1\frac{1}{2}$ ft. high, W. of cor.

From this corner, the $\frac{1}{4}$ sec. cor. of secs. 5 and 6, T. 27 N., R. 58 E., bears S. $0^{\circ} 21'$ W., 40.00 chs. dist. This $\frac{1}{4}$ sec. cor. is monumented with a firmly set iron post, 3 ins. diam., set by Biological Survey in 1936, with brass cap mkd.

44
 T27N R58E
 $\frac{1}{4}$
 S 6 | S 5
 1936

This corner is situated in a fence corner from which fences bear N. $63\frac{1}{2}^{\circ}$ E. and S. $41\frac{1}{2}^{\circ}$ W.

Land, rolling mountainous.

Soil, part sandy clay loam, part gravelly and rocky.

Timber, very scattering juniper; undergrowth, sagebrush, buck brush and native grasses.

Dependent Resurvey, Portion of the Subdivision of T. 28 N., R. 58 E.

Reestablishment of Surveys Executed by
 Hatch and Eaton, Deputy Surveyors, in 1869.

From the cor. of secs. 5, 6, 31 and 32, on the south boundary of the township.

N. $2^{\circ} 14'$ E., bet. secs. 31 and 32.

Over rolling land, through dense undergrowth; asc. gradually 30 ft. along E. slope.

39.99

The original $\frac{1}{4}$ sec. cor. of secs. 31 and 32, which is marked by a partly decayed and weathered juniper post, 1 in. diam., 25 ins. long, blazed on one side with marks nearly obliterated, lying on an old flat mound of earth.

At the corner point

Set an iron post, 3 ft. long, 1 in. diam., 28 ins. in the ground, with brass cap mkd.