

DEPENDENT RESURVEY OF A PORTION OF THE
5TH STAN. PAR. N., S. BDY. T. 26 N., R. 55 E.

Chains

Land, rolling mountainous and mountainous.
Soil, light sandy shallow mixed with clay and limestone and imbedded boulders; much loose rock on surface with coarse gravel.
Timber, scrub juniper interspersed with pinon pine.
Undergrowth, sagebrush, greasewood, buckbrush and briars.

S. 89° 34' W., along S. bdy. of sec. 31.

Over mountainous land, through dense undergrowth and scattering timber; asc. 140 ft. over NE. slope.

18.60 Slope changes to N.; asc. 105 ft.

31.10 Point of spur, projects N. 20° E.; desc. 10 ft.

36.20 Wash, course N. 20° E.; asc. 125 ft. over SE. slope.

39.96 The standard $\frac{1}{4}$ sec. cor., which is an iron post, 1 in. diam., 12 ins. above the ground, firmly set, marked and witnessed as described in the official record.

From this corner, the closing cor. of T. 25 N., Rs. 54 and 55 E., bears N. 86° 43' 47" W., 4.21 chs. dist., which is an iron post 3" diam., 20 ins. above the ground, firmly set in a mound of stone, marked and witnessed as described in the official record.

N. 89° 40' W.

Asc. 215 ft. over SE. slope.

16.24 Point of spur projects N.; desc. 160 ft. along NW. slope.

19.44 Enter dense juniper and pinon timber, bears N. and S.

35.34 Leave dense juniper and pinon timber, bears N. and S.

36.84 Wash, course N. 25° E.; asc. 15 ft.

40.76 The standard cor. of Tps. 26 N., Rs. 54 and 55 E., which is an iron post, 3 ins. diam., 12 ins. above the ground, firmly set, marked and witnessed as described in the official record.

Land, rough mountainous.

Soil, shallow sandy with much loose rock on surface and limestone outcropping; 4th rate.

Timber, juniper and pinon pine.

Undergrowth, sagebrush, buckbrush and briars.