

455

DEPENDENT RESURVEY OF SUBDIVISIONAL LINES T. 27 N., R. 55 E.

Chains

for the cor. for secs. 6 and 7, with brass cap mkd.

T27N	R55E
S6	S5
S7	

1939

of stone, 2 ft. base, $1\frac{1}{2}$ ft. high, W. of cor.

raise a mound

Thence, bet. secs. 5 and 6.

8.00

Shallow wash, course NE.

30.60

Wash, course NE.

31.00

Road, bears NE. and SW.

40.00

Record distance. No trace of old cor. found.

Set an iron post, 3 ft. long, 1 in. diam., 30 ins. in the ground, for the $\frac{1}{4}$ sec. cor. for sec. 5, only, with brass cap mkd.

$\frac{1}{4}$ S 5	
-------------------	--

1939

of stone, 2 ft. base, $1\frac{1}{2}$ ft. high, E. of cor.

raise a mound

42.22

Set an iron post, 3 ft. long, 1 in. diam., 30 ins. in the ground, for the $\frac{1}{4}$ sec. cor. for sec. 6, with brass cap mkd.

$\frac{1}{4}$ S 6	
-------------------	--

1939

of stone, 2 ft. base, $1\frac{1}{2}$ ft. high, W. of cor.

raise a mound

48.20

Road, bears E. and W.

63.30

Road, bears N. 50° E. and S. 50° W.

73.90

Wash, course N. 70° E.

80.48

The cor. of secs. 5, 6, 31 and 32, on the N. bdy. of the Tp.; an iron post, 2 ins. diam., 9 ins. above ground, mkd. and witnessed, as described in the field notes of the survey of T. 28 N., R. 55 E., surveyed under this group.

Land, nearly level and broken.

Soil, sandy silt; 2nd rate.

No timber; undergrowth, sagebrush and shadscale.

Grazing, fair.

SUBDIVISION OF T. 27 N., R. 55 E.

I commence the subdivisional survey at the cor. of secs. 3, 4, 33 and 34, on the S. bdy. of the Tp.; an iron post 2 ins. diam., 9 ins. above ground, mkd. and witnessed as described in the official and accepted field notes of the survey of T. 26 N., R. 55 E., surveyed under this group.

N. $0^\circ 11'$ E., bet. secs. 33 and 34.

Desc. 10 ft. over rolling land, on a N. slope, thru scattering timber and dense undergrowth.

7.40

Wash, course E.; over broken land.

21.60

Low spur, slopes E.; desc. 10 ft. over a N. slope.