	Independent Resurvey of the E. Bdy., T. 6 N., R. 65 E.
Chains	
	Set an iron post, 30 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd.
	T6N
	R65E R66E
	$\mathbf{S12} \left \frac{\mathbf{S}}{\mathbf{O19}} \right $
	S18
	1956
	Deposit broken glass around the iron post, 12 ins. below the surface of the ground.
40.00	Point for the ½ sec. cor. of sec. 12 only.
	Set an iron post, 30 ins. long, 2½ ins. diam., 24 ins. in the ground,
	with brass cap mkd.
* *	T6N
	R65E R66E
	S12
	1956
15.11	Deposit broken glass around the iron post, 12 ins. below the surface of the ground.
51.54	Point for the k sec. cor. of sec. 7, T. 6 N., R. 66 E.
a salah m	Set an iron post, 30 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd.
e .	
	74 T6N
	T65E R66E
	S 7
1	1956
	Deposit broken glass around the iron post, 12 ins. below the surface
* + 30 × (*) × × × × × × × × × × × × × × × × × × ×	of the ground.
80.00	Point for the cor. of secs. 1 and 12 only.
	Set an iron post, 30 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd.
_ d	T6N
4	R65E R66E
A 14 MOVE MA	$\frac{\mathbf{S} \cdot 1}{\mathbf{S} 12} \mathbf{S} \cdot 7$
	1956
,	Deposit broken glass around the iron post, 12 ins. below the surface of the ground.
	Tand manufactural
	Land, nearly level. Soil, sandy and gravelly loam. Timber, none; undergrowth, sagebrush and greasewood.
1	
	N. 0° 09' E., along the E. bdy. of sec. 1.
, v	Over nearly level land, through heavy undergrowth.
11.54	Point for the cor. of secs. 6 and 7, T. 6 N., R. 66 E.