

## Dependent Resurvey of a Portion of the N. Bdy., T. 3 N., R. 67 E., MDM.

Chains

T4N R67E  
 $\frac{1}{4}$  S32  
 T3N  
 1957

Deposit broken glass alongside iron post.

48.85 Wash, 10 lks. wide, 4 ft. deep, drains SW.

77.85 Wash, 10 lks. wide, 1 ft. deep, drains SW.

79.88 Point for the cor. of secs. 5 and 6 at proportionate dist.; there is no remaining evidence of the original cor.

Set an iron post, 30 ins. long,  $2\frac{1}{2}$  ins. diam., 22 ins. in the ground, with brass cap mkd.

T4N R67E  
 S32  
 S 6 | S 5  
 T3N  
 1957

Deposit broken glass alongside iron post.

Land, nearly level.

Soil, sandy and gravelly.

Timber, none.

Undergrowth, sagebrush.

N.  $89^{\circ} 49'$  W., along the N. bdy. of sec. 6.

Over nearly level land, general SW. drainage, through sagebrush.

4.16 Point for the cor. of secs. 31 and 32, T. 4 N., R. 67 E.

Set an iron post, 30 ins. long,  $2\frac{1}{2}$  ins. diam., 22 ins. in the ground, with brass cap mkd.

T4N R67E  
 S31 | S32  
 S 6  
 T3N  
 1957

Deposit broken glass alongside iron post.

39.94 Point for the  $\frac{1}{4}$  sec. cor. of sec. 6 at proportionate dist.; there is no remaining evidence of the original cor.

Set an iron post, 30 ins. long,  $2\frac{1}{2}$  ins. diam., 22 ins. in the ground, with brass cap mkd.

T4N  
 $\frac{1}{4}$  S 6  
 T3N R67E  
 1957

Deposit broken glass alongside iron post.

44.16 Point for the  $\frac{1}{4}$  sec. cor. of sec. 31, T. 4 N., R. 67 E.

Set an iron post, 30 ins. long,  $2\frac{1}{2}$  ins. diam., 22 ins. in the ground, with brass cap mkd.