Chains

described in the field notes of the independent resurvey of the Fourth Standard Parallel South executed under this group.

Land, nearly level desert. Soil, sandy; 2nd rate.

Timber, none.

Undergrowth, creosote brush, shadscale, buck brush and cactus. Grazing, poor.

INDEPENDENT RESURVEY OF WEST BOUNDARY OF T. 17 S., R. 64 E.

Independent Resurvey superseding the survey executed by R. H. Woods and W. H. Myrick, U. S. Deputy Surveyors, in 1881.

Beginning at the corner of Tos. 17 and 18 S., Rs. 63 and 64 E., which is an iron post, 3 ins. diam., firmly set, with brass cap marked and witnessed as described in the official record.

North, bet. secs. 31 and 36.

Over nearly level desert land, through scattering undergrowth, over a gentle NE. slope.

7.00 Flat wash, 25 lks. wide, course N.30°E.

39.80 Flat wash, 8 lks. wide, course N.15°E.

40.00 Set an iron post, 3 ft. long, 1 in. diam., 27 ins. in the ground, for $\frac{1}{4}$ sec. cor., with brass cap mkd.

s36 s31

1938

raise a mound

of stone, 2 ft. base, 1 ft. high, W. of cor.

From this corner, a limestone, 12x8x6 ins., marked \(\frac{1}{4} \) on W. face, bears N.17°30'E., 40 lks. dist. I remove the marks from this stone.

70.00 Enter Dry Lake bed, bears E. and W.

80.00 Set an iron post, 3 ft. long, 2 ins. diam., 27 ins. in the ground, for cor. of secs. 25, 30, 31 and 36, with brass cap mkd.

T178
R63E R64E
S25 | S30
S36 | S31

1938

raise a mound

of stone, 2 ft. base, 12 ft. high, W. of cor.

From this corner, a limestone, 10x10x5 ins., marked with 5 notches on the N. face, bears N.27°45'E. I remove the marks from this stone.

Land, nearly level desert; general drainage and exposure NE. into Dry Lake.

Soil, sandy and gravelly; 2nd to 3rd rate.

Timber, none.

Undergrowth, creosote brush, buck brush, and shadscale.

Grazing, poor.