

RESURVEY OF W. BDY. T. 24 S., R. 63 E.

Chains

North, bet. secs. 1 and 6.

Over slightly rolling land, draining generally SE., thru med. dense undergrowth.

14.50

Wash, 1 ch. wide, 10 ft. deep, course S. 30° E.

40.00

Set an iron post, 3 ft. long, 1 in. diam., 27 ins. in the ground, for $\frac{1}{4}$ sec. cor., with brass cap mkd.

$$\begin{array}{c} \frac{1}{4} \\ S1 \quad | \quad S6 \\ 1939 \end{array}$$

raise a mound
of stone, 2 ft. base, $1\frac{1}{2}$ ft. high, W. of cor.

81.90

Wash, 50 lks. wide, 4 ft. deep, course SE.

83.68

Intersect S. bdy. of sec. 31, T. 23 S., R. 63 E.

Set an iron post, 3 ft. long, 3 ins. diam., 27 ins. in the ground, for cor. of T. 24 S., Rs. 62 and 63 E., with brass cap mkd.

$$\begin{array}{c} T23S \quad R63E \\ \hline S31 \\ S1 \quad | \quad S6 \\ R62E \quad | \quad R63E \\ T24S \\ CC \\ 1939 \end{array}$$

raise a mound
of stone, 2 ft. base, $1\frac{1}{2}$ ft. high, S. of cor.

From this point, the cor. of T. 23 S., Rs. 62 and 63 E., bears S. 89° 54' W., 17.21 chs. dist., an iron post, 3 ins. diam., hereinbefore described.

Land, slightly rolling.

Soil, rocky; 4th rate.

Timber, none. Undergrowth, creosote.

Grazing, poor.

General Description

The land along the lines covered by these field notes varies from nearly level to broken mountainous. The soil is gravelly or alluvial 3d rate to rocky and sandy 4th rate. There is no timber. Undergrowth consists of creosote brush, cacti, weeds and bunch grass. Grazing is poor.