

64

Dependent Resurvey of the North Boundary of T. 4 S., R. 60 E.

Chains

From this cor., the original cor. of Ts. 3 and 4 S., Rs. 59 and 60 E., mkd. by a limestone 18x14x6 ins., firmly set in the ground, with dim marks on the edges, bears N. 89° 50' W., 239.30 chs. dist.

At the same point

Set an iron post, 30 ins. long, 2½ ins. diam., 8 ins. in the ground to solid rock, and in a mound of stone, with brass cap mkd.

T3S

R59E R60E

S36 | S31

S1 | S6

T4S

1958

Deposit the original stone alongside the iron post.

Land, rolling and broken bench.

Soil, gravelly to rocky clay loam.

Timber, none.

Undergrowth, sagebrush, rabbit brush, weeds and grass.

Survey of the East Boundary, T. 3 S., R. 60 E.

Beginning at the cor. of Ts. 3 and 4 S., Rs. 60 and 61 E.

Thence

North, along the E. bdy. of sec. 36.

Over mountainous land, through medium dense undergrowth; desc. along a NW. slope.

2.90 Wash, drains S. 70° W.; asc. along a SW. slope.

11.30 Spur, projects S. 60° W.; desc. along a NW. slope.

21.00 Wash, drains W.; asc. along a SW. slope.

25.10 Spur, projects S. 70° W. about 10 chs. to end; desc. along a NW. slope.

32.10 Wash, drains W.; asc. along a SW. slope.

40.00 Point for the ½ sec. cor. of sec. 36.

Set an iron post, 30 ins. long, 2½ ins. diam., 6 ins. in the ground to solid rock, and in a mound of stone, with brass cap mkd.

T3S

R60E R61E

½ S36

1958

Deposit broken glass at the base of the post.

Cont. ascent along a SW. slope.

41.50 Spur, projects W.; desc. along a NW. slope.

46.00 Wash, drains N. 60° W.; asc. along a SW. slope.