

Survey of the East Boundary of T. 3 S., R. 60 E.

Chains	
	<p style="text-align: center;">T3S W C R60E R61E ½S12 1958</p>
	Deposit broken glass at base of the post.
	Desc. along a NW. slope.
44.60	Wash, drains W.
57.20	Low spur, projects S. 70° W.; cont. along a broken W. slope.
70.50	Low spur, projects W.
78.30	Wash, drains W.; asc. along a SW. slope.
80.00	Point for the cor. of secs. 1 and 12.
	Set an iron post, 30 ins. long, 2½ ins. diam., 14 ins. in the ground to solid rock, and in a mound of stone, with brass cap mkd.
	<p style="text-align: center;">T3S R60E R61E S 1 ½S12 1958</p>
	Deposit broken glass at the base of the post.
	Land, rolling hills.
	Soil, sandy to rocky clay loam.
	Timber, none.
	Undergrowth, sagebrush, rabbit brush, weeds and grass.
	North, along the E. bdy. of sec. 1.
	Over rolling land, through medium dense undergrowth; asc. along a SW. slope.
12.60	Spur, projects SW.; desc. along a NW. slope.
21.20	Wash, drains S. 70° W.; asc. along a SE. slope.
39.70	Set an iron post, 30 ins. long, 2½ ins. diam.; 3 ins. in the ground to solid rock, and in a mound of stone, at the witness ¼ sec. cor. of sec. 1, with brass cap mkd.
	<p style="text-align: center;">W C T3S R60E R61E ½S1 1958</p>
	Deposit broken glass at the base of the post.
40.00	Point for the ¼ sec. cor. falls upon steeply sloping limestone ledge where the monument cannot be perpetuated.
42.60	Spur, projects S. 40° W.; desc. along a NW. slope.
80.00	Point for the cor. of Ts. 2 and 3 S., R. 60 E.
	Set an iron post, 30 ins. long, 2½ ins. diam., 4 ins. in the ground to solid rock, and in a mound of stone, with brass cap mkd.