

Survey of the East Boundary of T. 6 S., R. 62 E.

Chains	<p>Corner is situated on crest of a flat spur which slopes ENE. from NW.</p> <p>Land, part rolling to broken, part nearly level. Soil, sandy to rocky clay loam. Timber, scattered juniper and Joshua trees; undergrowth, sagebrush, greasewood, and cacti.</p>
	<p>North, bet. secs. 1 and 6.</p> <p>Over gently rolling bench top, through scattered timber and undergrowth.</p>
15.30	<p>NE. crest of bench, bears NW. and SE.; desc. 250 ft. over NE. slope.</p>
27.80	<p>Wash, 30 lks. wide, 3 ft. deep, in canyon, course SE.; asc. 115 ft. over SW. slope.</p>
40.00	<p>Point for the $\frac{1}{4}$ sec. cor. of secs. 1 and 6, falls on barren rock.</p> <p>Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., over an X marked on barren rock surface, supported in a mound of stone, 5 ft. base, 30 ins. high, with brass cap mkd.</p> <div>$\frac{1}{4}$ S 1 S 6 1953</div> <p>No auxiliary accessory.</p> <p>Asc. 115 ft. over SW. slope.</p>
43.00	<p>Crest of steep ascent, bears NW. and SE.; change to a gradual S. slope; asc. 90 ft. over same.</p>
59.40	<p>Spur, slopes E. from mesa crest which bears W., 2 chs. dist.; thence along E. slope.</p>
62.30	<p>Change to NE. slope; desc. 140 ft. over same.</p>
73.50	<p>Wash, 30 lks. wide, in vertically sided ravine, 40 ft. deep, course ENE.; asc. 85 ft. over broken SE. slope.</p>
80.00	<p>Point for the cor. of Ts. 5 and 6 S., Rs. 62 and 63 E., falls on barren rock surface.</p> <p>Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., over an X marked on bare rock surface, and supported in a mound of stone, 4 ft. base, 30 ins. high, with brass cap mkd.</p> <div>T5S R62E R63E <u>S36 S31</u> S1 S6 T6S 1953</div> <p>No auxiliary accessory.</p> <p>Land, part gently rolling desert, part rocky and broken. Soil, sandy to rocky clay loam. Timber, scattering juniper and Joshua trees; undergrowth, sagebrush, greasewood, blackbrush, Spanish dagger, and cacti.</p>