-	Dependent Resurvey, Portion of East Bdy., T. 21 S., R. 60 E.
Chains	1951 from ties obtained from Bell Telephone Company. The telephone company recovered this cor. in 1941 or 1942 and it is shown on telephone right of way map "R.O.W.Ap.No. CCO21488", filed in 1953.
	At the corner point
	Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 18 ins. in the ground, with brass cap mkd.
	S 13 S 18 1955
	Bury the wooden hub alongside, and raise a mound of stone, 3 ft. base, 1 ft. high, around the iron post.
	N. 0° 37' E., beginning new measurement.
1.41	Telephone line, bears N. 27° 57' W. and S. 27° 57' E., parallel dirt road along NE. side of telephone line.
20.49	Point for the N. 1/16 sec. cor. of secs. 13 and 18, at proportionate distance; falls near center line of oiled road bearing E. and W.
	At the corner point
	Set a 20d spike, flush with road surface.
	from which
	A reference point bears N. 31° 28' E., 47 lks. dist., marked by an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., set 24 ins. in the ground and in a mound of stone to top, with brass cap mkd.
	R P 1955
40.98	The cor. of secs. 7, 12, 13 and 18, monumented with an iron post, $2\frac{1}{2}$ ins. diam., firmly set, mkd. and witnessed as described in the record of the 1952 resurvey of T. 21 S., R. 61 E.
8	Land, rolling and broken. Soil, sandy. Vegetation, scattered creosote bush, salt brush, and cactus.
	Dependent Resurvey, 5th Stan. Par. S., along a Portion of S. Bdy. of Township 20 South, Range 60 East
	Reestablishment of the Survey Executed By Brunt and Proctor, Deputy Surveyors, in 1881.
	From the standard $\frac{1}{4}$ sec. cor. of sec. 32, on the S. bdy. of T. 20 S., R. 60 E., mkd. by an iron post, $2\frac{1}{2}$ ins. diam., set, mkd. and witnessed as described in the record of the 1952 resurvey of a portion of the S. bdy. of T. 20 S., R. 60 E.
	S. 89° 35' W., on the S. bdy. of sec. 32.
	Over rising to level valley land.
40.18	The standard cor. of secs. 31 and 32, identified and restored by Cartographer Lewis in 1954, who found the corner point marked by a limestone, 16x14x6 ins., marked with 6 grooves on N., 5 grooves on E. and 1 groove on W. face, firmly set and surrounded by a low mound of stone, where he

U. S. GOVERNMENT PRINTING OFFICE 16-28520-1