

## Dependent Resurvey, South Three Miles of East Boundary, T. 43 N., R. 36 E.

## Chains

Reestablishment of the Survey Executed by  
Deputy Surveyor O. A. Palmer in 1868.

Beginning at the cor. of Ts. 42 and 43 N., Rs. 36 and 37 E., which is marked by an iron post,  $2\frac{1}{2}$  ins. diam., firmly set, marked and witnessed as described in the field notes of the 1954 resurvey of T. 42 N., R. 37 E.

N.  $0^{\circ} 32'$  W., bet. secs. 31 and 36.

Over nearly level land.

25.50 Unimproved road, bears N.  $43\frac{1}{2}^{\circ}$  W. and S.  $43\frac{1}{2}^{\circ}$  E.

39.84 Point for the  $\frac{1}{4}$  sec. cor. of secs. 31 and 36, at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 30 ins. long,  $2\frac{1}{2}$  ins. diam., 24 ins. in the ground, with brass cap mkd.

$\frac{1}{4}$   
 S36|S31  
 1954

Bury a granite stone, 6x5x2 ins. mkd. X, alongside the iron post.

79.68 Point for the cor. of secs. 25, 30, 31 and 36, at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 30 ins. long,  $2\frac{1}{2}$  ins. diam., 24 ins. in the ground, with brass cap mkd.

T43N  
 R36E R37 E  
 S25|S30  
 S36|S31  
 1954

Bury a granite stone, 7x5x2 ins. mkd. X, alongside the iron post.

Land, nearly level.

Soil, alkaline loam.

Vegetation, scattering greasewood, salt brush and salt grass.

No timber.

N.  $0^{\circ} 32'$  W., bet. secs. 25 and 30.

Over nearly level land.

22.25 Graded road, bears N.  $73^{\circ}$  W. and S.  $73^{\circ}$  E.

39.84 Point for the  $\frac{1}{4}$  sec. cor. of secs. 25 and 30, at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 30 ins. long,  $2\frac{1}{2}$  ins. diam., 24 ins. in the ground, with brass cap mkd.

$\frac{1}{4}$   
 S25|S30  
 1954

Bury a granite stone, 5x4x2 ins. mkd. X, alongside the iron post.