

Dependent Resurvey of the 8th Standard Parallel North, on the South Boundary
of T. 41 N., R. 37 E.

Chains

Reestablishment of the Survey Executed by
Deputy Surveyor O. A. Palmer in 1868.

Beginning at the standard cor. of Ts. 41 N., Rs. 37 and 38 E., marked by an iron post, 3 ins. diam., firmly set, marked and witnessed as described in the official record of the survey of T. 41 N., R. 38 E.

N. 89° 21' W., on the S. bdy. of sec. 36.

Descend over broken slopes of rolling mountainous land draining SW.

- 0.38 The closing cor. of Ts. 40 N., Rs. 37 and 38 E., marked by an iron post, 3 ins. diam., firmly set, marked and witnessed as described in the official record of the survey of T. 40 N., R. 38 E.
- 13.60 Dry wash, drains SW.
- 40.06 The standard $\frac{1}{4}$ sec. cor. of sec. 36, which is at the center point of an ancient and well defined mound of stones.
- At the corner point.
- Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 24 ins. in the ground, with brass cap mkd.
- SC
 $\frac{1}{4}$ S36
1954
- Bury an igneous rock, 6x4x2 ins. mkd. X, at base of the iron post.
- S. 89° 35' W., beginning new measurement.
- Continue descent over broken slopes of rolling mountainous land draining SW.
- 5.00 Unimproved road, bears N. 65° E. and S. 65° W.; Chimney Creek, dry, drains SW.
- 23.80 U. S. Highway No. 95, an oil surfaced road, bears N. 35 $\frac{1}{2}$ ° W. and S. 35 $\frac{1}{2}$ ° E.
- 27.70 Wire fence bounding BLM reseeding area, parallels highway.
- 38.68 The standard cor. of secs. 35 and 36, marked by the partially decayed remains of the original willow stake in the center of an old and well defined mound of stones.
- At the corner point.
- Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 24 ins. in the ground, with brass cap mkd.
- SC
T41N R37E
S35 | S36
1954
- Bury an igneous stone, 7x4x3 ins. mkd. X, and the remains of the old corner stake alongside the iron post.
- Land, rolling and mountainous.
Soil, stony clay-loam.
Vegetation, sagebrush and rabbit brush.
No timber.