

Dependent Resurvey of a Portion of the West Boundary, T. 43 N., R. 37 E.

Chains	<u>Reestablishment of survey executed by O. A. Palmer, 1868</u>												
	<p>From the corner of secs. 13, 18, 19, and 24, Ts. 43 N., Rs. 36 and 37 E., on the west boundary of the township, which is monumented with an iron post, 2½ ins. diam., 6 ins. above the ground, firmly set, marked and witnessed as described in the official record.</p> <p>N. 0° 22' E., along the west boundary of sec. 18.</p> <p>Over nearly level land through heavy undergrowth.</p>												
7.30	Road, on curve, bears NE. and NW.												
13.70	Well, with windmill, bears E., 1.10 chs. dist.												
19.60	Road, bears E. and W.												
19.70	Fence, four strand barbed wire, with steel and cedar posts, bears E. and W.												
40.14	<p>Point for the ¼ sec. cor. of secs. 13 and 18 at proportionate distance, there is no remaining evidence of the original corner.</p> <p>Set an iron post, 30 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap marked</p> <div style="text-align: center;"> <p>¼</p> <table border="0"> <tr> <td>S 13</td> <td> </td> <td>S 18</td> </tr> <tr> <td colspan="3">1955</td> </tr> </table> </div> <p>Deposit broken glass alongside the iron post, 12 ins. below the surface of the ground.</p>	S 13		S 18	1955								
S 13		S 18											
1955													
80.28	<p>Point for the cor. of secs. 7, 12, 13, and 18 at proportionate distance. There is no remaining evidence of the original corner.</p> <p>Set an iron post, 30 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap marked</p> <div style="text-align: center;"> <p>T43N</p> <table border="0"> <tr> <td>R36E</td> <td> </td> <td>R37E</td> </tr> <tr> <td>S12</td> <td> </td> <td>S7</td> </tr> <tr> <td>S13</td> <td> </td> <td>S18</td> </tr> <tr> <td colspan="3">1955</td> </tr> </table> </div> <p>Deposit broken glass alongside the iron post, 12 ins. below the surface of the ground.</p> <p>Land, nearly level. Soil, sandy and gravelly loam. No timber. Undergrowth, sagebrush and greasewood.</p>	R36E		R37E	S12		S7	S13		S18	1955		
R36E		R37E											
S12		S7											
S13		S18											
1955													
18.50	<p>N. 0° 22' E., along the west boundary of sec. 7.</p> <p>Over nearly level land, through heavy undergrowth.</p> <p>Well, with windmill and large cement ditch, bears W., 50 lks. dist.</p>												
19.73	Well, bears W., 70 lks. dist.												