

## Dependent Resurvey of a Portion of the West Boundary, T. 43 N., R. 37 E.

## Chains

22.73 Fence, five strand barbed wire, with cedar posts, bears E. and W.

34.70 Leave heavy sagebrush, edge bears NE. and SW.; continue across open grass land.

40.14 Point for the  $\frac{1}{4}$  sec. cor. of secs. 7 and 12 at proportionate distance. There is no remaining evidence of the original corner.

Set an iron post, 30 ins. long,  $2\frac{1}{2}$  ins. diam., 24 ins. in the ground, with brass cap marked

$\frac{1}{4}$

S 12 | S 7

1955

Deposit broken glass alongside the iron post, 12 ins. below the surface of the ground.

74.90 Fence, four strand barbed wire, with cedar posts, bears E. and W. Enter heavy undergrowth.

80.28 Point for the cor. of secs. 1, 6, 7, and 12 at proportionate distance. There is no remaining evidence of the original corner.

Set an iron post, 30 ins. long,  $2\frac{1}{2}$  ins. diam., 24 ins. in the ground, with brass cap marked

T43N

R36E | R37E

S1 | S6

S12 | S7

1955

Deposit broken glass alongside the iron post, 12 ins. below the surface of the ground.

Land, nearly level.

Soil, sandy loam.

No timber.

Undergrowth, sagebrush and greasewood.

N.  $0^{\circ} 22'$  E., along the west boundary of sec. 6.

Over nearly level land.

14.55 Road, bears E. and W.

40.14 Point for the  $\frac{1}{4}$  sec. cor. of secs. 1 and 6 at proportionate distance. There is no remaining evidence of the original corner.

Set an iron post, 30 ins. long,  $2\frac{1}{2}$  ins. diam., 24 ins. in the ground, with brass cap marked

$\frac{1}{4}$

S 1 | S 6

1955

Deposit broken glass alongside the iron post, 12 ins. below the surface of the ground.

42.35 Fence, five strand smooth wire fence, with cedar posts, bears E. and W.