

174

Dependent Resurvey of the 9th Standard Parallel
North through R. 37 E.

Chains

Reestablishment of the survey executed by O. A. Palmer in 1868.

Beginning at the standard corner of T. 46 N., Rs. 37 and 38 E., which is mkd. with a grey stone, 12x7x8 ins., above ground, firmly set and mkd. with 6 notches on the E. and S. edges as described in the official record.

At the corner point

Set an iron post, 30 ins. long, 2½ ins. diam., 22 ins. in the ground, with brass cap mkd.

SC
T46N
R37E R38E
S36 | S31
1956

Deposit broken glass at base of post.

Reset original corner stone along side.

N. 89° 38' W., along the S. bdy. of sec. 36.

Over nearly level land, through heavy undergrowth.

4.57 Point for the closing cor. of T. 45 N., Rs. 37 and 38 E., hereinafter described.

40.13 Point for the standard ¼ sec. cor. of sec. 36, at proportionate dist.; there is no remaining evidence of the original corner.

Set an iron post, 30 ins. long, 2½ ins. diam., 23 ins. in the ground, with brass cap mkd.

SC
T46N R37E
¼ S36
1956

Deposit broken glass at base of post.

44.67 Point for the ¼ sec. cor. of sec. 1, T. 45 N., R. 37 E., hereinafter described.

80.27 Point for the standard sec. cor. of secs. 35 and 36, at proportionate dist.; there is no remaining evidence of the original corner.

Set an iron post, 30 ins. long, 2½ ins. diam., 22 ins. in the ground, with brass cap mkd.

SC
T46N R37E
S35 | S36
1956

Deposit broken glass at base of post.

Land, nearly level.

Soil, sandy.

Timber, none; undergrowth, sagebrush.

N. 89° 38' W., along the S. bdy. of sec. 35.

Over nearly level land, through moderate undergrowth.