

182

Dependent Resurvey of the S. Bdy., T. 45 N., R. 37 E.

Chains

Deposit broken glass at base of post.

Set a cottonwood post, 6 ft. long, 5 ins. diam., alongside.

Land, level.

Soil, sandy.

Timber, none; undergrowth, sagebrush, rabbit brush and rye grass.

N. 89° 16' W., bet. secs. 5 and 32.

Over river bottom land, through heavy undergrowth.

- 2.97 Wire fence, bears N. 45° E. and S. 45° W.
- 11.67 Slough, dry, 25 lks. wide, 6 ft. deep, drains SW.
- 40.76 Point for the $\frac{1}{4}$ sec. cor. of secs. 5 and 32, at proportionate dist.; there is no remaining evidence of the original corner.
- Set an iron post, 30 ins. long, 2½ ins. diam., 22 ins. in the ground, with brass cap mkd.

T45N R37E

$\frac{1}{4}$ $\frac{S32}{S 5}$
T44N
1956

Deposit broken glass at base of post.

Set a cottonwood post, 5 ft. long, 3 ins. diam., alongside.

Over level bottom land, through heavy undergrowth.

- 46.92 Quinn River to N., approx. 5 chs. dist., course W.
- 52.72 Sage and river bottom line, bears NW. and E.
- 76.92 Sage and river bottom line, reenter river bottom, line bears N. and S.
- 81.52 Point for the cor. of secs. 5, 6, 31 and 32, at proportionate dist.; there is no remaining evidence of the original corner.
- Set an iron post, 30 ins. long, 2½ ins. diam., 22 ins. in the ground, with brass cap mkd.

T45N R37E

$\frac{S31}{S 6}$ | $\frac{S32}{S 5}$
T44N
1956

Deposit broken glass at base of post.

Set a cottonwood post, 5 ft. long, 4 ins. diam., alongside.

Land, level.

Soil, sandy.

Timber, none; undergrowth, sagebrush, Nevada sage, rye grass and rabbit brush.

N. 89° 16' W., bet. secs. 6 and 31.

Over river bottom, through heavy undergrowth.